

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00047484 Account # - R-	Description/Serial Number A6857515 Model 700 Center Fire Caliber: 270 ADL	Date Received - 6/24/2002 Estimate Date - 6/10/2002 Current Date - 6/28/2002
Customer DWAIN LUNA CENTER HILL SPORTS MARINA 7457 SPARTA HWY SPARTA, TN 38583 US Phone (H) (931)-761-3196 Phone (W)	Return To DWAIN LUNA CENTER HILL SPORTS MARINA 7457 SPARTA HWY SPARTA, TN 38583 US Fax Email	

Reported		Problems Found	
M238	CLEAN & INSPECT	M123	FORWARD TO PRODUCT SERVICE FO
M992	FIRE WHILE UNLOADING	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
Problem/Notes	Concern - Went off when unloading, read it could be fixed. Fault Found - Action dirty. All 3 adjustment screws re-set. Clean action and replace trig assem \$20.00. D.S.


Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
Service Total:		22	

10 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO: DWAIN LUNA
CENTER HILL SPORTS MARINA
7457 SPARTA HWY
SPARTA TN 38583-4193




TN 385 4-00



UPS GROUND

TRACKING #: 1Z 114 813 03 1190 3358



BILLING: PREPAID

INV#: RE00047484

ASC 3.70 J69X/J64X 14.0 01/2002