

RECEIVING AND ESTIMATING REPORT

COMMENTS

To Product Service

ORDER

R 94-36689

INITIAL
JJMCUSTOMER ORDER NO.
5491

W/SEE THRU MOUNTS

DATE RECEIVED
12/13/94DATE OPENED
12/19/94DATE CODE
PV 6-79SERIAL NUMBER
A6767284

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

BDL

ACCESSORIES

W/STUDS

FROM:

LESLIE EDELMAN OF NJ
ROUTE 309
BOX 536
MONTGOMERYVILLE

PA 18936

SHIP TO:

LESLIE EDELMAN OF NJ
ROUTE 309
BOX 536
MONTGOMERYVILLE

PA 18936

CUST NO: 005966 WILM L

ACCOUNT NUMBER

063103

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

*11/16/95**So vinyl
clean & fast*

REPAIR CHARGE

20

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

28.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

*Mfgn 6/74 Unable to disp locate customer concern as noted.
Receiver, bolt, guard screws and trigger Assy noted as such*

PARTS

Trigger Assy

COMMENTS

*Trigger pull measured 4 1/2 LBS as
Rec'd. spec. 4.0 - 5.0*
** Replace washers with adhesive backed
spacers.*
*See owners manual for proper
cleaning and maintenance*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS04000