

Set up file

RECEIVING AND ESTIMATING REPORT				COMMENTS		Product Service		ORDER NO.
INITIAL FPS	CUSTOMER ORDER NO.	W/VALOR 2.5		SCOPE & LENS COVER				R 94-2384
DATE RECEIVED 08/16/94	DATE OPENED 08/17/94	DATE CODE AS 3-69	SERIAL NUMBER 1622884	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	ADJ.		
ACCESSORIES SLING STRAP W/STUDS		W/STUDS		SCOPE MNTS		SCOPE BASE		
FROM: MORALES, DIORIS 9040 FORT HAMILTON PKWY BROOKLYN NY 11209				SHIP TO: MORALES, DIORIS 9040 FORT HAMILTON PKWY BROOKLYN NY 11209				
ACCOUNT NUMBER		ACCOUNT NUMBER NC		CUST NO. 01457 C.O.D.		PROM. DATE		ESTIMATED
GUN CONDITION		WRITE		VIA		UPS		
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						REPAIR CHARGE 30.00		
						EXCISE		
						TAX		
						INSURANCE		
						UPS		8.00
						PARCEL POST		
						TOTAL		38.00
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT		
CYCLE	A1	B1						
TRIGGER GROUP		B2			E1	F1		
BOLT ASSY.		B3				F2		
BARREL ASSY.		B4		D1	E3	F3		
REC. ASSY.		B5		D2	E4	F4		
WOOD			C1	D3	E5	F5		
METAL			C2					
MAIN FAULT <i>Upon receipt, we could not duplicate the report concern. Examination</i> <i>revealed that the trigger and trigger assembly appeared a good assembly. A heavy build up</i> <i>of safety compound was noted. The same compound was seen when we set</i> <i>the rifle up.</i>								
PARTS	COMMENTS <i>Replace the complete trigger assembly</i> <i>with the trigger at 1/2 normal</i> <i>replacement cost as per order of good will</i> <i>Go ahead</i>							
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN			
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE			
OFFICE COPY								

RD6925 REV.

to A/S
8/19/94