

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER
R 94-35107

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/02/94

12/06/94

PC 6-82

B6390515

700

7MMAG

BDL/LH

ACCESSORIES

W/STDS

SCOPE BASE

L/SIGHTS

FROM:

MELTON, DOUG
107 DOLLAR CIRCLE
P O BOX 38
FLORISSANT

CO 80816

SHIP TO:

MELTON, DOUG
107 DOLLAR CIRCLE
P O BOX 38
FLORISSANT

CO

80816

CUST NO: 109824 C.F.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WHITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

280

to meet
clean & fast

CUSTOMER CONCERN	AMMO	FUNCTION	FIT	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP	B2				E1	F1
BOLT ASSY.					E2	
BARREL ASSY.	B4			D1	E3	F3
REC ASSY.						F4
WOOD				D3	E5	F5
METAL						

MAIN FAULT

Mfg. 6-82 Fault & fire as recd. Then when safe is pushed it fires. Trigger has been adjusted outside of the factory and the trigger assy. pin real was driven thru receiver too far and was interfering with the safety arm, causing it above customer concern. Exchange trigger assy. at a special price as a gesture of good will.

PARTS

Trigger Assy.

COMMENTS

Unable to minime trigger pull as recd. Force left was .0125

* Replace washers with adhesive backed springs

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

R06-15 REV. 1/94

PS04218