

RECEIVING AND ESTIMATING REPORT

COMMENTS

*to Product Service*ORDER
R 93-25211

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/16/93

11/19/93

RC 11-82

B6140572

788

308 WIN

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

Setup
MILLERS GUN CENTER INC
JACKSON & DUPONT HWY
NEW CASTLE

DE 19720

MILLERS GUN CENTER INC
JACKSON & DUPONT HWY
NEW CASTLEDE
19720

CUST NO 000616 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

B5

WOOD

METAL

C2

MAIN FAULT

Left mfg 1982, upon receipt, unable to duplicate customer concern. Upon inspection, the action and trigger assembly are correct and light rust, and change safety resistance. Safety assembly works more than normal, have repaired. Left under good cleaning.

PARTS

COMMENTS

*Replace complete trigger assembly
Clean action, at 1/2 normal repair
cost, as further good work*

Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6825 REV. 1/9

PS04427