

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-16548

INITIAL
JJMCUSTOMER ORDER NO.
6012ATTN JACK KAST
BBL CHANGED OUTSIDE FACTORY *KCF.5.*

DATE RECEIVED

05/24/94

DATE OPENED

05/24/94

DATE CODE

SERIAL NUMBER

B6469332

NEW SERIAL NUMBER

MODEL AND GRADE

700 280

BDL/LH

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

ON TARGET INC
6984 W MAIN ST
KALAMAZOO

MI 49009

SHIP TO:

ON TARGET INC
6984 W MAIN ST
KALAMAZOOMI
49009

CUST NO: 002454 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

Gun Went Off when safety was flipped

When report we were unable to duplicate the customer concern. Examination did not show that the contact on the trigger adjustment screw was not adjusted. The trigger pull measured below our min. spec. Trigger pull changing.

PARTS

*5mm rifle - .014**#26345 Trigger Assembly*

COMMENTS

*Replaced trigger assembly and when action set to normal operation, no further adjustment needed.**Go ahead*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

R 6925 REV 1/8

PS04667