

Set up file

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL FPS	CUSTOMER ORDER NO			<i>-XC FS</i>		R 94-13438	
DATE RECEIVED 04/18/94	DATE OPENED 04/19/94	DATE CODE RE 11-84	SERIAL NUMBER 7639670			NEW SERIAL NUMBER	MODEL AND GRADE 7 7MM-08
ACCESSORIES W/STUDS		SCOPE BASE L/REAR SIGHT					
FROM: PENN, RON 1111 ROUTE 6N WATERFORD PA 16441				SHIP TO: PENN, RON 1111 ROUTE 6N WATERFORD PA 16441			
CUST NO: 096164 CLO.D							
ACCOUNT NUMBER 0591001		ACCOUNT NUMBER ME		FROM DATE		ESTIMATED	
GUN CONDITION		WRITE <input type="checkbox"/>		VIA		UPS	
<input type="checkbox"/> NEW <input checked="" type="checkbox"/> LIGHTLY WORN <input type="checkbox"/> WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> UNREPAIRABLE <input type="checkbox"/> MARRED				REPAIR CHARGE		EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3					
BARREL ASSY.		B4			E3	F3	
REC. ASSY.		B5			E4	F4	
WOOD			C1	D3	E5	F5	
METAL			C2				
MAIN FAULT							
<p><i>Upon receipt could not duplicate concern. However, examination noted a thick layer of grease accumulated inside the trigger housing and on both sides of the safety lever. Cleaned and found pull adjustment screws loose. Also, safety lever pin not seated.</i></p>							
PARTS				REMARKS			
<i># 22345 trigger housing 90458</i>				<i>Trigger pull measured 3 1/2 to 3 3/4 lbs all steel. Some light wear. O.K.</i>			
<i>Bando Lee</i>				<i>Positive complete trigger assembly and clean action at 1/2 normal adjustment. Not as quiet as I would like.</i>			
<i>New #</i>				<i>Jo Mear</i>			
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE		

OFFICE COPY

RD8825 REV 1/94

to A/S
5/19/94