

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDEF
R 94-20359

INITIAL

CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

07/06/94

07/07/94

WD 8-77

A6491903

700 270

ADL

ACCESSORIES

W/STUDS

L/REAR SIGHT

Product Service

FROM:

SHIP TO:

PRESNELLS GEN MERCHANDISE INC
RT 4 BOX 690
MARION NC 28752PRESNELLS GEN MERCHANDISE INC
RT 4 BOX 690
MARION NC 28752

CUST NO: 011225 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Could not determine the above concern. However, the information received
out on the basis of the above fault, action, and on the inspection. The
trigger group is also found with dirt and a heavy buildup of residue.
The trigger group with the above fault - 4 to the trigger group.

PARTS

COMMENTS

Parts complete. Trigger group and
clean action (but promise) at 1/2
normal speed. Not a great improvement.

JP [Signature]

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
REP		☒	☒		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD8825 REV. 1/84