

RECEIVING AND ESTIMATING REPORT			COMMENTS			ORDER NO. R 92-03077		
INITIAL	CUSTOMER ORDER NO.		W/LEUPOLD 2X7 SCOPE & SEE THRU SCOPE MNTS					
FPS	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE		
	01/17/92	01/24/92	WI	A6346902		700 30-06		ADL
ACCESSORIES W/STUDS								

FROM	SHIP TO:
PAYNE, CLAYTON L 1360 GIBSON DRIVE BIRMINGHAM AL 35214	PAYNE, CLAYTON L 1360 GIBSON DRIVE BIRMINGHAM AL 35214

ACCOUNT NUMBER	ACCOUNT NUMBER MC	CUST NO: 056921 C.O.D L	PROM DATE	ESTIMATED	VIA
		WRITE ☒ CLEAN/TEST			UPS

GUN CONDITION	REPAIR CHARGE
☐ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Cannot duplicate complaint after many attempts. Removed of barrel action from stock for safety shot of cleaning oil, in underside of metal. Trigger assembly is extremely oily & dirty.*

Trigger pull 3 1/2 pounds; rear sight .007"

PARTS	COMMENTS
	<i>Chute along most trigger group if possible. If not, offer to replace trigger assembly at a reduced cost, as a gesture of good will.</i>
	<i>Return scope & mts in cabinet</i>

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
<i>03</i>					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE