

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-13497

INITIAL
TAL

CUSTOMER ORDER NO.

DATE RECEIVED
04/18/94DATE OPENED
04/19/94DATE CODE
CZ 04-75SERIAL NUMBER
6856453

NEW SERIAL NUMBER

MODEL AND GRADE

700 25-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

RENO, JAY A.
2323 FOURTH STREET
SANTA ROSA

CA 95404

SHIP TO:

RENO, JAY A.
2323 FOURTH STREET
SANTA ROSA

CA

95404

CUST NO 96167 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3				
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, we found no apparent function. Shot usually
has hangover before difficult to disassemble. Has not been cleaned in years
for proper cleaning. Apparently, the number that all 3 trigger adjustment screw have
been set - not. Some adjustment screw should be moved inward.

PARTS

COMMENTS

#26345 trigger has been off.
Trigger pull measured 2 3/4 to 3 1/2
lbs as tested and left was .0085
Barrel complete trigger assembly
and then action at 1/2 normal adjustment
test as function of good will
good

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD925 REV. 1/94

PS05165