

RECEIVING AND ESTIMATING REPORT

#36

INITIAL JJM	CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 10/25/90	DATE OPENED 10/29/90	DATE CODE KI 5-88	SERIAL NUMBER C6252382	MODEL AND GRADE 700 30-06 ADL/LS		ORDER R 90-28270
ACCESSORIES W/STUDS						

FROM:

RUTTY, STEPHEN E
RD #2
BOX 240
CANTON PA 17724

SHIP TO:

RUTTY, STEPHEN E
RD #2
BOX 240
CANTON

PA
17724

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☒ LIKE NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"i.e. moving the safety across the rifle to fire"

MAIN FAULT

Trigger assembly rusted from unknown source.
Internal trigger parts not moving freely

PARTS	Replace trigger assembly at no-charge, as gesture of good-will					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

104925 REV. 7/80