

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 95-28788

INITIAL FPS	CUSTOMER ORDER NO.	CALL TAG ATTN: DENNIS SANITA			
DATE RECEIVED 11/10/95	DATE OPENED 11/14/95	DATE CODE	SERIAL NUMBER 7624265	NEW SERIAL NUMBER	MODEL AND GRADE 7 243 WIN
ACCESSORIES W/STUDS					

FROM:

SAVOIE, TOMMY
248 LINDA STREET
HOUMA

LA 70364

SHIP TO:

SAVOIE, TOMMY
248 LINDA STREET
HOUMALA
70364

CUST NO: 131079 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 3081502	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION			REPAIR CHARGE		
<input type="checkbox"/> NEW			EXCISE		
<input checked="" type="checkbox"/> LIGHTLY WORN			TAX		
<input type="checkbox"/> WORN			INSURANCE		
<input type="checkbox"/> VERY WORN			UPS		
<input type="checkbox"/> UNREPAIRABLE			PARCEL POST		
<input type="checkbox"/> MARRED			TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP					E1	F1
BOLT ASSY.						F2
BARREL ASSY.					V3	F3
REC. ASSY.				D2	L4	F4
WOOD			C1	D3	L5	F5
METAL			C2			

MAIN FAULT Upon receipt we could not duplicate the Customer reported concern. However, our elimination revealed that all 3 trigger adjustment screws have the locknut removed and appear to have been tampered with. More than normal force required to move safe was also noted.

PARTS	COMMENTS				
# 92458	Replace the complete trigger assembly at N/C, as a gesture of good will				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS05397