

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO		COMMENTS	
JJM				ATTN J STEKL	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
01/10/91	01/16/91	CF 4-85	B6698158	700 270 ADL	R 91-01504
ACCESSORIES		W/STUDS			

FROM:

SHARBONO, FRANCES
401 E BOXELDER APT 304
GILLETTE WY 82716

SHIP TO:

SHARBONO, FRANCES
401 E BOXELDER APT 304
GILLETTE WY 82716

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM DATE	ESTIMATED	VIA
						UPS

R CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

OWNER'S REQUEST: *It is the safety that looks up*

AULT: *Higher than normal safety - if force. Sec-employment has been adjusted outside of policy, which is excessive.*

Since the safety-off force appears to be too high, replace the trigger assembly at no-charge, as a gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV 7/90

PS05527