

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 98-24232

INITIAL CUSTOMER ORDER NO

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

/13/98

11/16/98

WP 8-95

E6848309

700

7MMAG

ADL/SYN

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM

SHIP TO

SILVER, BERRY G
1122 NAGEL
ST MARYS

OH 45885

SILVER, BERRY G
1122 NAGEL
ST MARYSOH
45885

CUST NO:063400 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER

WRITE

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Inspection revealed rust under the safety detent spring and on the trigger pin from unknown source.

PARTS

COMMENTS

Supply replacement m/700BDL 7mm mag (6039)
DW# _____
in spring

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 7-97

PS05622