

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-00306

INITIAL CUSTOMER ORDER NO

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

2/28/98

01/06/99

CR 4-97

D6259377

700 30-06

BDL/DM

ACCESSORIES

W/STUDS

L/CLIP

FROM

SHIP TO:

SHAMBACH, HARRY E
RR 1
1 ZION CHURCH RD
MIDDLEBURG

PA 17842

SHAMBACH, HARRY E
RR 1
1 ZION CHURCH RD
MIDDLEBURGPA
17842

CUST NO: 172848 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NO

230145

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

REL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Upon receipt we could not duplicate the reported concern,
but our Wom. would verify the trigger group was
on top & side of receiver. *Explain to customer*

PARTS

COMMENTS

26345

Explain the complete trigger
assembly when the action is
no longer a question of function

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 7.97

PS05635