

CEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-36345

CUSTOMER ORDER NO

ATTN TOM NAGLE CALL TAG

RECEIVED 09/94	DATE OPENED 12/16/94	DATE CODE RQ 11-78	SERIAL NUMBER A6664759	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MMAG	BDL/LH
SERIES L/SIGHTS			SCOPE BASE			

SHIP TO.

SWATZYNA, RON J
2757 WHITE OAK DR
GRAND PRAIRIE

TX 75052-4457

SWATZYNA, RON J
2757 WHITE OAK DR
GRAND PRAIRIETX
75052

CUST NO. 110620 C.M.D.L.

QNT NUMBER	ACCOUNT NUMBER N/C 059015	WRITE ☐	PROM DATE	ESTIMATED 12-19	VIA UPS
CONDITION					REPAIR CHARGE
NEW					EXCISE
SLIGHTLY WORN					TAX
WORN					INSURANCE
VERY WORN					UPS
UNREPAIRABLE					PARCEL POST
REPAIRED					TOTAL

COMPONENT CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	B1				
TRIGGER GROUP		B2				
ASSY.						
REL ASSY.		B4		D1	E	
ASSY.				D2		
D			C1		D3	
L			C2			

FAULT: Could not duplicate customer's concern as received. Trigger pull was measured at 2.25 - 2.50 LBS - Well below factory spec. Trigger life measured at .009. All trigger engagement screws have been re-set inside of factory. Sealant is missing from all screws and screws have been "staked" at screw slots. Bolt stop pin and screw are not painted in the normal direction, indicating that trigger housing was disassembled outside of factory 12-19-94. Replaced at r/c per picture of trigger pull 12-19-94.

COMMENTS

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/94

PS05696