

COMMENTS

ORDER
R 94-35679

AL	CUSTOMER ORDER NO
----	-------------------

ATTN JACK KAST

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
10/1/94	12/11/94	DR 9-68	369743		700 7MMMAG BDL
ISSUES	11/STUDS				

SHIP TO:

SIMONS SPORT SHOP
2840 HWY 10
MOUNDS VIEW

MN 5442

STIMONS SPORT SHOP
2840 HWY 10
MOUNDS VIEW

MN
55412

CUST NO: 002862 ILJONL

UNIT NUMBER	ACCOUNT NUMBER N/C <i>059015</i>	WRITE ☐	PROM DATE	ESTIMATED	VIA UPS
-------------	-------------------------------------	--------------------------------	-----------	-----------	-------------------

CONDITION

EW

GH LY WORN

WORN

ERY WORN

NREPAIRABLE

IARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

	TOTAL	
--	-------	--

TOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
---------------	------	----------	--------	----------	-----	---------

JE	B1				
GER GROUP					
ASSY.	B2		E2		F2
REL ASSY.			E3		F3
ASSY.			D2	F4	F4
D		C1	D3	5	F5
		C2			

²AULT After 4/1/85 Trigger was sluggish and firing pin was slow to fall, the first time in rec'd.. Sear, trigger, trigger side plates and connector were gummed up with solidified oil's not allowing sear to drop reliably on the trigger and connector to actuate after trigger was pulled. Exchange trigger Assy at N/C strictly as a gesture of good will.

COMMENTS

Engineer Assy complete

See owner's manual for ^{PROPER} cleaning and maintenance.

REPAIRMAN	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

FD6925 REV 1/94

OFFICE COPY

PS05762