

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R92-00507

INITIALS CUSTOMER ORDER NO.

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/30/91

01/07/92

XE 12-84

B6638383

700 270

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM

SHIP TO:

SERVISTAR SPORTSMAN REPAIR
& HARDWARE
7045 PARKLANE RD
COLUMBIA
USA

SC 29204

SERVISTAR SPORTSMAN REPAIR
& HARDWARE
7045 PARKLANE RD
COLUMBIA
USA

SC 29204

CUST NO: 028775 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER NYC

WRITE

☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

1-23-92

UPS

GUN CONDITION

- ☒ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

Fires

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Rifle will malfunction as described in attached letter. Disassembly of rifle revealed that trigger assembly contains internal rust and trigger and connector will remain in pulled condition due to binding of rust. Internal parts not moving nor functioning properly.

PARTS

COMMENTS

Replace trigger at no-charge,
asa genuine goodwill

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV 8/91

PS05873