

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00072178	Description/Serial Number 7777152	Repairman - Carl Cotton
Account # - R-	Model 7 Center Fire Caliber: 300 SA	Date Received - 11/3/2003
	ULTRA MAG LS	Estimate Date -
		Current Date - 11/5/2003
Customer TARGETMASTER 255 RT 202 N		Return To TARGETMASTER 255 RT 202 N
CHADDS FORD. PA 19317 US		CHADDS FORD. PA 19317 US
Phone (H) (610)-459-5400		Fax (610)-459-3607
Phone (W)		Email

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M122	RUSTED COMPONENT
M992	FIRING PIN FALLS WHEN SAFE IS RELEASED		

Material #		MaterialDesc	Repair			
			Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F92458	7	TRIGGER ASSB	1	1	0	N
Part Total:			1	1	0	
Service						
4000294		GR-CHECK TPA	1	1	0	Y
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000119		GR-TEST	1	1	0	N
Service Total:			2	2	0	

Problem/Notes	The trigger and trigger pin are rusty, from being poorly maintained. Replacing trigger assy. at 1/2 MSP				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date