Remington Arms Co., Inc. Product Service Legal Case #:5089

				Lega	Case #:5089								
Case Inform	nation												
RE#	RE# Date Opened		Date Opene	d(PS)	Date Closed	]	Incident Date Pro			Lit	Lit	0	bsolete
213942 12/10/2010		0/2010	11/15/201	10	0 12/14/2010		11/13/2	2010					
Customer Ir	nformation												
Туре	Business	First Name	Last Name	Street	(	City	State	Zip	Age		Con		
<b>.</b>				20 Hemloc	D. 0'll	*11	<b>D</b> 4	10535			/ 610-2		
Incident		Ross	Bentley	20 memoc	CDr. Gilbe	ertsville	PA	19525			c 610-3		
Incident Inf	formation										1020@	John	oustinet
Claims	ion manon		Codes		Repair	Est.	Med	ical Tre	atment		Med	ical S	Status
PI			cours		nopun	1.54	littu	ivai 170	aunent		IVICU	ieur i	otatas
PD		Cause:4015	Improper Main	tenance									
S			Fired on Safe R					Unknov	wn				
C FSR													
	<b>.</b> .	11- J TTo stat	ed he was @ the	range on 11/	13/10 & had a	FSR. No	damage	- No in	iurv. df				
11/15/10: C	Justomer ca	illed in. He stat	cu ne was ag uk	, runge on 11/					J J				
		illed in. He stat					1997 W.H. (Mart Martin Constraints)		<b>j j</b>				
	formation	nied in. He stat	Type		Mode	ł/Ga.	1.94° W	SK		Se	rial H	bl.	DOM
Firearm Info	formation				n na manana ang kanana				U				
Firearm Info Mfg. Remingt	Formation ton		Туре		Mode	0 WIN	(	<b>SK</b> 257	U				
Firearm Info Mfg. Remingt	formation ton <b>hased</b>	Whe	Type CF/BA		<b>Mode</b> 700/27 <b>Acces</b>	0 WIN sories		<b>SK</b> 257	U 791 I Owner				
Firearm Info Mfg.	formation ton hased DIC	Whe CKS CLOTHIN	Type CF/BA re Purchased	IG GOODS	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	CU 191 I Owner	E627	6092 1	KQ :	5/21/199
Firearm Info Mfg. Remingt Date Purcl	formation ton hased J:FSR	Whe CKS CLOTHIN	Type CF/BA re Purchased NG & SPORTIN	IG GOODS	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	CU 191 I Owner	E627	6092 1	KQ :	5/21/199
Firearm Info Mfg. Remingt Date Purch CONCERN Ammunition	formation ton hased JI:FSR on Informati	Whe CKS CLOTHIN	Type CF/BA re Purchased NG & SPORTIN	IG GOODS	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	CU 191 I Owner	E627	6092 1	KQ :	5/21/199
Firearm Info Mfg. Remingt Date Purch CONCERN Ammunition Other Produ	formation ton hased J:FSR n Informati	Whe CKS CLOTHIN	Type CF/BA re Purchased NG & SPORTIN	IG GOODS	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	CU 191 I Owner	E627	6092 1	KQ :	5/21/199
Firearm Info Mfg. Remingt Date Purch CONCERN Ammunition Other Produ	formation ton hased J:FSR n Informati	Whe CKS CLOTHIN	Type CF/BA re Purchased NG & SPORTIN	ig goods	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	CU 191 I Owner	E627	6092 1	KQ :	5/21/199
Firearm Info Mfg. Remingt Date Purch CONCERN Ammunition Other Produ Settlement	formation ton hased J:FSR on Informati ucts Inform	Whe CKS CLOTHIN ion - None Def ation - None D	Type CF/BA re Purchased NG & SPORTIN ined efined	IG GOODS Reming	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	CU 191 I Owner	E627	6092 1	Q :	5/21/1994 Cash
Firearm Info Mfg. Remingt Date Purch CONCERN Ammunition Other Produ Settlement	formation ton hased J:FSR n Informati	Whe CKS CLOTHIN ion - None Def ation - None D	Type CF/BA re Purchased NG & SPORTIN	IG GOODS Reming	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	U 191 I Owner I	E627	6092 H		5/21/199
Firearm Info Mfg. Remingt Date Purch CONCERN Ammunition Other Produ Settlement Settlement Per Ilion -	formation ton hased J:FSR on Informati ucts Inform	Whe CKS CLOTHIN ion - None Def ation - None D Rele	Type CF/BA re Purchased NG & SPORTIN ined efined	IG GOODS Reming	Mode 700/27 Acces TWO PIECE S	0 WIN sories SCOPE E	BASE	SK 257 Driginal N	U 191 I Owner I	E627	6092 I		5/21/199 Cash Date

11/15/10: Sending ARS, ltr, form & box. Box order # 1159263. df 12/17/10: Per Ilion - Could not duplicate concern. TA & trigger pin rusty, dirty. Action is dirty. Replace TA, clean, test fire @ 1/2 normal cost - quote. df 12/17/10: I emailed the quote to customer. df

#### Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
· · · · · · · · · · ·	Examiner		<b>B.TRAVIS</b>
	Exam Date		12/14/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4041	Defective Ammunition Casing	POOR MAINTENENCE
	Description		22" 270 WIN
	Date Code		KQ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
1	I <u>r</u>		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5089&Type=Case

12/17/2010

•

.

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	BOLT IS VERY RUSTY
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	RUSTY ACTION
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFET
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	RUSTY
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Functioning	RUSTY,DIRTY
Trigger	Pull	Select	6.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

	QUOTATION
	<b>ROOINION</b>

#### Remington Arms Company, Inc. 870 Remington Dr. P.O. Box 700

870 Remington Dr. P.O. Box 700 Madison, NC 27025-0700 www.remington.com info@remington.com ESTIMATING REPORT

Parts/Repairs

.

Fax

J

800-243-9700 336-548-7801

### ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order N	umber	Description/Serial Nu	mber		Date Ree	ceived -	12/11/2010
RE00213942		E6276092			Estimate		12/16/2010
Account # - R-					Current	Date -	12/17/2010
Customer				Return To			
ROSS BENTI				ROSS BE		цс	
20 HEMLOC	K DKIVE			20 HEML	UCK DR	IVE	
GILBERTSV	ILLE. PA 19525 US			GILBERT	SVILLE.	PA 1952	5 US
Phone (H) ( Phone (W)	(610)-316-3184		Fax Email	DIXIE20@	COMCAS	ST.NET	
Please Circle On	-						
VISA MC AM PO Number	IEX DISCOVER Card No	•		Exp. D	ate		
	)	Time To Call		Onen	Acct. R		
Approval: Custo	mer Signature			Open	<u></u>		
If You De	esire Any Change Please Use 7	The Reverse Side For Yo	our Comments	And Mark Th	is Box		
	No	tice: We process checks ele	ctronically throu	igh Check 21			<u></u>
and de la porte de la seconda de		Proble	ms	and the second se		de de la come	
Reported			Eound Tax				
M123	FORWARD TO PRODU	CT SERVICE	M123	FORW	ARD TO F	PRODUCT	SERVICE F
	FOR INSPECTIO						
		Technician's	Comments a		<u> Astronom</u>		
ProblemNotes	could not duplicate cond	cern,trigger assembly	and trigpin r	usty, dirty, act	ion rusty.P	leplace trig	ger
	assembly, clean and test	fire at 1/2 normal cost	t per product	service.	-		-
						. <u>.</u>	
S. L. M. Str. St.	Estimate **C.O.D./S	hipping and Handling	Charges are	NOT, Included	l in this Qu	iote	5
<u>Material #</u>	Material Description		<u>Qty</u>	Warranty		Discount	Extended
Part				<u>Y/N</u>	<u>Unit</u>	Percent	<u>Amt</u>
	X-MARK PRO 700 TRIG A	ASSB RH BLACK (O	1	N	\$94.00	50%	\$47.00
Service			-			50,0	÷
4000114	GR-SHIPPING & HANDL	NG (GUN REPAIR)	1	N	\$17.00	50%	\$8.50
	GR-TEST		1	N	\$23.00	50%	\$11.50
4000294	GR-CHECK TPA		1	Y	\$17.00	0%	\$0.00
				S	Sub Total:		\$67.00
				E	st. Sales Ta	x:	\$4.02
				C	Grand Tota	l:	\$71.02

#### Fulcher, Dell Marie

From: To: Sent: Subject:

,

,

postmaster@remington.com dixie20@comcast.net Friday, December 17, 2010 5:15 PM Relayed: Ross Bentley - Ref# 5089

.

Delivery to these recipients or distribution lists is complete, but delivery notification was not sent by the destination:

dixie20@comcast.net

Subject: Ross Bentley - Ref# 5089

	l Repair		te Repair E	xpedite Rep	iair Inquiry	Repair Too		Tools R	eports	Table Maintenance	System	Location
								Entresistantes de la composition de la c		· .		
				Marine								
1	📳 frmR	Elnquiry	- Repair Inqu	iry	aulare - Sourceare	and a second second						
	ante de las	- 146 23 Sec	THE SOUTH OF	ar in the Association	6276092 Model	700 Cantor Fr				511 - 1745 - 1757 - 1757 - 1757 - 1757 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757 - 1757	54.442 71.744 () 91.744 ()	
	1. Jac. 12. 19	10.00	<b>1E00213942</b>	WIN P	oduced: 05/21/1	996 SKU. 25791	s (Caliber 27	13.50				C C C C C C C C C C C C C C C C C C C
	N <sup>64</sup> Verily					ingen av de service de la s La service de la service de		S S	tatus N	w 12/11/2010 7 32 45	AM ACCURATE	
	*it ADDR	ESS INFOR	MATION -	C. L. S. S. W	No. Company	Received from	Return				UN GEALTAN	
		N. 6. 6. 8.	USS BENTLEY			HECEIVED IION 4	A48 - 649 - 51 - 66 - 26		场业的代码	CRecen	ved rrom	
	小売業		DHEMLOCK DR	IVE	<u></u>			LOCK DRIVI	<u>e</u> E			
	Sec. 12. 30	Iress 2			RO,Box	—¥983				PO Box		
		City	ILBERTSVILLE				GILBER	TSVILLE				
		State: P	A Zip Code:	19525	Country		PA	Zip Code:	19525	Country		
	3.5. 11	SC 25 LAN				N.SFFL:			at it as the second		<u>Kana kana kana kana kana kana kana kana </u>	
	Contac	1 / Condition	Dichlems I. F	etimates Histo	ry / Status, Ship	2 Trans Carlos	877 Y.G	¢ITO,S				
		ARCE 2			<b>《外期</b> 的事件》(199			-510-5104		Current State		
					(Desc1	<u>, and an </u>		C Shipping	N. 101 SIL	New	State Barrier	
<b>3</b>	10.22	11/2010.7		sanguinegf	Repair Added		ľ		1 Sec. 1	12/11/2010 7 . sanguine		
	av	11/2010 7:	Expedite EmailSent	sanguinegf ArmEmail	From: Check In Repair Receive	d D	J.  S	<b>Γ</b> ;Parts Re	A. R. 19	Repair Be	nch 29.5	
	₩. —		EmailVerified		Receipt		MEDIOCI	∏ Passed I		Repair Loca		
	· · · · · · · · · · · · · · · · · · ·	14/2010 9:		Travisbw	Repair Maintena		atus: New	∏ (Rètun a ∏ Has Bee	dia to be a set	Contracting Contracting Course	tion 🦾	
	9759			A WOLS	1			I cinternal I		Transfer Nun	nbei 👘	
					的活动的							
	Ber	air Sea								Refresh	Close	
ł	2	n in der der der der der							30 3		State and service in	<u>元28%。</u> (1) 
					and the second sec				ÇQ.254.1			

有效的人们,这些正常不能正确的现在,我们们是不可能的,我们们是不是这些的问题,我们是没有的问题,我们是没有的问题,我们们就是这些,我们们就是不是不能能。"他们们是	and a second
	and the second
Start 🖉 2 Microsoft 🖓 🖓 Microsoft 🦿 😭 2 Microsoft 🦿 😜 Part Search b 🖓 🖓 SAP Logon 710 🔤 🌈 My Excite - W 🔅 🛠 frmReperMai 🤻	

 الله	<u> </u>	 کر کر ک		I.
Ń	DEC	1 7	⊾ ♥ _ 7 2010	
R	γ.			

COPY 0

November 15, 2010

Ross Bentley 20 Hemlock Dr. Gilbertsville, PA 19525 Ph: 610-316-3184

Ref: # 5089

Dear Mr. Bentley,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington, H&R customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700 Fax: 336-548-7872

enclosure



Could Not duplicate concern T.A. + Trip pin Rusty, Dirty, Action Musty. Replace TPA, cleAREN Test Pine At 1/2 Noriwal cost, Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com Factory Repair Form

۲.,

Print	Reset					
Model	Serial					
Number: 700	Number: E6276092					
Are you the original ow	ner?: 🖸 YES 🕱 NO					
Name: ROSS BENTLEY	Date of Purchase: Given to me Don't Reember date					
Address (no						
20 Hemlock Or	rive					
City: Gilbertsville	State: <i>PA</i> Zip: 19525					
Phone (Daytime): <u>6/0 3/6 3/8 4</u>	Fax: MA					
E-mail Address:(if e-mail address is provid be sent) Dixie 20 @ Com	The second se					
E-mail A						
🖺 I would like to receive future e						
Please describe your proble	em and date of occurrence:					
Rifle fired Twice in at Taken off, 11/14/2010 Same Thing happened o	ow when safety was it home the next bay ot every time safety wis					
released 11/15/2010						
NOW THERE DOESNIT SEE I DON'T TRUST SAFETY.	m To be a problem but 12/30/2010					
.500 cha	racters left					
Ammunition Information:						
Manufacturer: RemingTon	Type: Express CORE-LOKT					
Other (i.e. bullet weight/type, shot size, powder): , 270 /50 Gテ・						
Handload In	formation:					
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					

Reloader Used:

http://www.remington.com/asp/factory\_repair\_form.asp

Bullet Type/Shot Size:

11/12/2010

Page 1 of 3

<u>, '</u>,

•

Brand of cleaning solution used: ມາບໍ່ KNOW
How often do you clean the bore? (Months or Number of rounds) Rare(y
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds) Nevec
Brand of lubricant used: N/A
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site of in our owners manual? > YES 🕅 NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
<ul> <li>Record the serial number of your firearm before sending it.</li> <li>Pack your firearm for safety and to prevent further damage in shipping and handling Preferably,</li> <li>ship in a firearm box. (Note: Original boxes may not be returned.)</li> <li>Remove all accessories from your firearm to prevent loss or damage.</li> <li>Provide a return address on both the outside and inside the box. Shipments without proper</li> </ul>

11/12/2010

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

(.

,

Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of NEWGUN rounds)					
How often do you clean the action? (Months or Number of NEເວິດ rounds)					
How often do you clean the trigger assembly? (Months or Number of ルビン Gun rounds)					
Brand of lubricant used: New BUN Remoil					
How often do you lubricate the bore? (Months or Number of Newform rounds)					
How often do you lubricate the action? (Months or Number of New rounds)					
How often do you lubricate the trigger assembly? (Months or Number of New GJm rounds)					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >  YES INO					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)					
What were the services					
performed?) New Gun					
Ship your INSURED firearm by either UPS or Parcel Post to:					
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.					
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper					

11/12/2010



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:		11/15/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	A(10 lbs
RUEASEICHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 5089 Rifle	<u></u>		

## LABEL INFORMATION

MAIL LABEL TO: Ross Bentley 20 Hemlock Dr. Gilbertsville, PA 19525 Ph: 610-316-3184

RETURN ITEM TC Remington Arms Attn: Product Service Ilion, NY

RUEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION IS THE

 4XX596
 NOV 15, 2010
 ALL CURR USD
 1 OF 1

 SVC GNDCOM
 ACT WT 10.0 LBS
 1 OF 1

 TRACKINGH 1Z4XX5969067628129
 REF 1:ROSS BENTLEY/CD/DMF
 REF 1:ROSS BENTLEY/CD/DMF

 REF 1:ROSS BENTLEY/CD/DMF
 REF 2:5089/RIFLE
 SINGLE-PIECE PUB RATE CHRGS:
 SVC T/P USD

 DV 0.00
 COD
 0.00
 RS 0.50
 0.00

 AH 0.00
 PR
 0.00
 SP 0.00
 TOT PUB CHG 7.42











