Remington Arms Co., Inc. Product Service Legal Case #:4654

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

202217 9/8/2010 7/29/2010 10/22/2010

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Dan Dobbs 824 Echo Valley Glendale WV 26038 H 304-845-7550

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD shot hole in gas wall

PD shot hole in gas wan furnace Cause:4015 Improper Maintenance Concern:1008 Fired on Bolt Closing

Unknown

S C

7/29/10 Per call from Dobbs, he was loading the rifle in the house to shoot at a groundhog that has been eating his fruit trees. He was having problems with the safety movement. He pulled the trigger and it didn't fire. He took it to another room and unloaded it and reloaded and it fired putting a hole in his gas wall furnace. He says it looks like two holes but the glass may have made one hole. He is the original owner and bought it about 4-5 yrs ago at Ace Sptg Goods. It has only had about 1 1/2 box of shells through it. No one hurt.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/223 REM
 27514
 E6532137 LT 2/10/1999

Date Purchased Where Purchased Accessories Original Owner

Date Fulcional Actional Company Company Arrold Company Company

4/29/1999 ACUSPORT CORPORATION SCOPE,RINGS,BASE Y

CONCERN:FBC,PROPERTY DAMAGE

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Settlement Release Date Release Date Reimbursement Release Date Release Date Reimbursement Release Date Reimbursement Release Date Release Date

Repair at no charge as goodwill

Repair/Replacement Repair/Replacement
Cost Date

ust Dat

7.23 10/25/2010

7/29/10 Sending ARS.cm 9/10/10 Called Dobbs and told him the condition of the trigger and safety. We can repair the rifle at no charge but this was not due to a defect and we would not cover the damage to the heater. He will call me back.cm 9/17 Dobbs left me a voice message asking if we could take care of replacing the rifle and the cost for the furnace and door before he contacted an attorney. I called but had to leave a message on his voice mail to call me. I will offer to repair but no other.cm 10/7/10 Left another voice message for Dobbs to call me.cm 10/22/10 Dobbs called and he had watched CNBC broadcast. Wants us to cover rifle and furnace. I again went over the rust and adjustments of his rifle and that we would repair his rifle as goodwill but it was not a defect from the factory or under warranty and we would not pay for the furnace. He'll contact a lawyer. We will take pictures and return the rifle.cm 10/25/10 Dobbs left voice message to replace the trigger and send back.cm

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4654&Type=Case

10/25/2010

Page 2 of 3


. Examination[Remington/CF/BA]


Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date]	9/9/2010
Examination	Product Type]	RF
	Action Type		A
Examination Cause Barrel Extractor Locking Overall	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	
	Description		24" 223 REM
	Date Code		LT
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4654&Type=Case

10/25/2010


	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear		Like new; Functioning	
Feeding Test	Togto	Test Fired	False
Feeding Test	Tests	False	
		Slightly Worn; Not Functioning	WILL FOLLOW DOWN TRIG AND TRIG PIN RUSTED SAFETY RUSTED TRIG WILL NOT RETURN
T	Pull	Select	5.5#
Trigger	Altered	True	TRIG PULL SCREW ALTERED
	IISub. Accembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE







	aylin Repairs								Calculation and a second s	
File Add R	epair Estimate Re	pair Expedite Repair	Inquiry Repa	air Tools CSR Tools	Reports	Table Maintenance	System			
•	•				.,		;;			
							Walter .			
	•	del	ع العند		7/1			A. Santa		
				Down as .		•				
		Donnie Inquier	· · · · · · · · · · · · · · · · · · ·		Service Andrews			neik Tenk	กับได้	
		Repair Inquiry		20127 Maria 200 Canada		777	asia G managan	<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	2	
		epair Number: RE002022 Venly Repair	REM Proc	532137 Model 700 Center Juced: 02/10/1999	rse Lamber	223 Repairman Status Pa	skèd 9/9/2010 10:11			
	- 1 W	ADDRESS INFORMATION				Janus, Ira	akeu 37 37 2010 10 1	JO AM		A.
		Customer		Received fro		11 10 10 10 10 10 10 10 10 10 10 10 10 1	C Re	cerved from -		
		Name: DAN DOBBS Address 1: 824 ECHO VA	LLEY	<u> </u>	25.24	DOBBS CHO VALLEY	<u></u>			
	f = f	Address 2.		0 Box J			PO Bok			
		City GLEN DALE State: WV Zip Co	26038	Country: US	GLEN	DALE Zip Code: 26038	Country: US	- 7		
		200	A Chicago	J FFL:	7.5					
		ontact / Condition Problems	Estimate History					neo provinciana (*).	H rs.	
		Date Code	/UserID	Desc1 Desc2	1,360,000	T: Shipping Hald	Current S	ilatus ked		
		1/9/201012:50 New	valentds	Repair Added		∏ ∤Interface Hold	9/9/2010 1			
		9/8/2010 12:5 Expedite 9/8/2010 5:05 EmailSen	valentds ni ArmEmail	From: Check In To: Repair Received DANDO	BBS82	J → Estimate Sent T ∘ Parts Received	Trav Product Repair Li	Services		
		9/8/2010 5 05 Email/eri		Receipt DANDO		☐ Passed Inspection ☐ Return as Receive		N		
•		9/9/2010 10:1 Maint .	Travisbw		E stimating	☐ Has Been Approve	,,,,,,	N Same of the same	j.	
		9/9/2010 10:1 ParkedE	xt Travisbw	Placed in PS B hold for	disposii [▼] [] Internal Repair	Payment	wanter		7
•		Repair Search		TERMINAL STREET			Refresh	Clase		
		al to describe the second second				12 H D 2 1 1 1		30.3		
	35	Section 1					and the same	200		
			along Williams	dest	. gover gan provide would	1000	1			
					to the oracle	and the second second second	many and the second			
			100		#FI					
		•								
			• •							
Supryfl	ILN/Prod	frmRep	oarMain		Ď	1102R7XPIL		Thursday, Sep 9 20	10 29	AM
a start	@ Calendar	vitros 🗐 Vints Sa	greener (Option in the	Oum	s=Marlin(Rep.#			. ⊘©®(¢)≡©	20: 100-1104A



4659

4724° 555 3013

July 29, 2010

Dan Dobbs 824 Echo Valley Glendale, WV 26038

Subject: Case # 4654, Model 700

Dear Mr. Dobbs,

Per our conversation, enclosed is a UPS prepaid shipping label for shipment of the firearm for inspection. Complete the enclosed form and enclose it inside with the firearm before shipping along with the 2nd copy of my letter.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator

Phone: 800-243-9700 ext 8684

E-mail: christy.mitchell@remington.com

enclosure



RE00202217

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

On July 28, 2010, I loaded my 223 rifle with a shell to shoot a groundhog. I pulled the trigger and nothing happened. I loaded the gun once more and just as I closed the breach the gun fired. The bullet hit the gas furnace then Rica shaded off and hit the door. The door would cost \$300 for material and labor to replace. The gas furnace to replace would be \$600 for material and labor. I'm lucky to be alive and didn't kill anyone else. I want a new 223 and everything replaced. I have also enclosed pictures of the damaged property.

Sincerely,

Dan Dobbs

Call me if you have guestions or concerns about the gun or replacing the property.

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700	Serial Number: E 65 3	32137				
Are you the original owner?: X YES NO						
Name: Pan Dobbs <>	Date of Purchase: 4 - 3	29-1999				
Address (no PO Boxes): 824 ECHO YA	lley					
City: GIEN DAIE	State: WY	zip: 26038				
Phone (Daytime): 304845-7550	Fax:					
E-mail Address: (if e-mail address is provided, notification sent) dandoldos 240 comcast.	of receipt and shipment will be 그란	•				
E-mail Address:						
I would like to receive future e-mail updates from Ren						
Please describe your problem and date of occurrence:		<i>(</i> ₽				
See enclosed little	X C .	<u>.</u> <u>∰</u>				
500 characters left		<u>.X</u>				
Ammunition Information:						
Manufacturer: Winchester	Type: 223 REV	<u> </u>				
Other (i.e. bullet weight/type, shot size, powder): Bal	listic Silverti	055 grain				
Handload Information:						
Powder Used:	Powder Weight:					
Case/Hull Used:	Primer Used:					
Bullet Type/Shot Size:	Reloader Used:					
		4				

ţ.

1.51

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: OUter5
How often do you clean the bore? (Months or Number of rounds) EVERY box of 20 shells
How often do you clean the action? (Months of Number of rounds) ENCRY BOX of 205 hell S
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used Preministon REM Oil with tellow
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds) FUERY X GO hUntin
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

Remington Arms Co., Inc. Product Service Legal Case #:4654

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

7/29/2010

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Dan Dobbs 824 Echo Valley Glendale WV 26038 H 304-845-7550

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD shot hole in gas wall furnace

Cause:4079 Other - Unexamined Concern:1008 Fired on Bolt Closing

Unknown

S C

7/29/10 Per call from Dobbs, he was loading the rifle in the house to shoot at a groundhog that has been eating his fruit trees. He was having problems with the safety movement. He pulled the trigger and it didn't fire. He took it to another room and unloaded it and reloaded and it fired putting a hole in his gas wall furnace. He says it looks like two holes but the glass may have made one hole. He is the original owner and bought it about 4-5 yrs ago at Ace Sptg Goods. It has only had about 1 1/2 box of shells through it. No one hurt.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/223
 27514
 E6532137
 2/10/1999

Date Purchased Where Purchased Accessories Original Owner

ACUSPORT CORPORATION Y

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Repair/Replacement Cost Repair/Replacement Date

7/29/10 Sending ARS.cm 8/4/10 Needs abox, Sent on ord # 1/24813. cm

Examination[Remington/CF/BA]

Part Sub-Part Code Comment

July 29, 2010

Dan Dobbs 824 Echo Valley Glendale, WV 26038

Subject: Case # 4654, Model 700

Dear Mr. Dobbs,

Per our conversation, enclosed is a UPS prepaid shipping label for shipment of the firearm for inspection. Complete the enclosed form and enclose it inside with the firearm before shipping along with the 2^{nd} copy of my letter.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you as a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator

Phone: 800-243-9700 ext 8684

E-mail: christy.mitchell@remington.com

enclosure

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

••	Gase#	4654	- Date-of-Cal	1/29/10	Date of		PreLit Lit	@bs	
)	Reporter name address				Incident Name/Age address	Pe	an Dobbs	Valley	
	contact #'s		·		contact #'s	G/e	24 Echo 24 Echo 20 Jale h	N 26 638	* .
	email		ole in		email	30	9-895		
	Injury Medical Treatment	gar wa	11 tur	nace	-2.	holes			
	Alleged								
	Firearm	Ser# E633137	Cal - 223	DOM	Orig owner?	When/W	There purchased	45 yx	
_)	Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Additional info		
	Other Product Was 90	ing to doot a	groundho	a pull	ed 4	~/99en	rididis	Fire 50	went
	Thats b	per eating fruit oad in	/h / .	d aff	hous-	e. id 4	Satety us shells to	yould'it	to Unload I reload
		Only po	it a	-box o	+ 1/2	of.	shells ti	trough it	<i>y-1</i> 0-1-0
	Notes:								
	Customer's Request								
	My actions/ offers								



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	7/29/2010 REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKAG	E:	10
PLEASE GHEOKONE MEDIA COORDINATOR TO MAIL	I WILL MAIL	xx	
DESCRIPTION:	700		

LABEL INFORMATION

MAIL LABEL TO:	Dan Dobbs 824 Echo Valley Glendale, WV 26038		
RETURN ITEM TO	: Rem Product Service		

TRILEASE COMPLETE ALLEPARTIS OF THIS FORM: AND SEND TO THE MEDIA COORDINATION:

4XX596 JUL SERVICE GNDCOM		ALL (CURR USD	1 0	F
TRACKING# 124XX59		B5B			
REF 1:DAN DOBBS/C					
REF 2:REF#700					
HANDLING CHARGE 0	.00				
SINGLE-PIECE PUB	RATE CHR	GS:	SVC	T/P USD	
DV 0.00	COD	0.00	RS	0.50	
DC 0.00	DGD	0.00	SD	0.00	
AH 0.00	PR	0.00	SP	0.00	
TOT PUB CHG 8.24		PUB+HAND	OLING	8.24	