

Remington Arms Co., Inc.
Product Service
Legal Case #:7020

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
249469	12/7/2011	12/8/2011	12/8/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Nagel Gun Shop, Inc		Nagel Gun Shop,	6201 San Pedro	San Antonio	TX	78216		W 210-342-5420

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on bolt closing Concern:1008 Fired on Bolt Closing			
C				

1/5/12 Per note with rifle, round stuck in chamber, rifle fired closing bolt. Round sticks in chamber after being fired.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	20000	A6364436	EI	10/1/1976
Date Purchased	Where Purchased	Accessories	Original Owner			
	BERNS WHLSE DENVER CO		U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire under BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	40.40	1/5/2012				

1/5/12 Per Ilion, could not duplicate concern. Trigger assm dirty. Replace TPA, clean and test fire under BLSM program price of \$20 + shipping.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/8/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		EI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	5#
	Altered	True	PULL SCREW ALTERED
	Sub-Assembly	M/700 Bolt Lock	

NAGEL GUN SHOP, INC.

PURCHASE ORDER

No 79799

Wholesale Distributors
6201 SAN PEDRO
SAN ANTONIO, TEXAS 78216
(210) 342-5420

7020

SHOW ORDER NUMBER
ON YOUR INVOICE

11 30 20 11

22"
EI 10/7
54
008

ARM SERVICES
14 HOFFLER AVE
ILLION, NY. 13357

PLEASE SHIP VIA

QUANTITY	ITEM	PRICE
1	REMINGTON 700 ADL DELUX 270WIN S/N # A6364436	
	REPAIR # 29849	
	REMINGTON UPS SHIPPING LABEL	
	Q ROUND STUCK IN CHAMBER, RIFLE FIRED CLOSING BOLT, ROUND STICKS IN CHAMBER AFTER BEING FIRED REPAIR OR REPLACE UNDER WARR.	
	THANKS	

NAGEL GUN SHOP, INC.
by G. A. Funnis

RECEIVED
DEC 13 2011

BY:

Number: A6364436
Model: 700

RE00249469

could not duplicate concern.
T.A. dirty. Replace TPA, clean +
test fire under BLP ROR & 20.
+ ship

(polish chamber)







