

Remington Arms Co., Inc.
Product Service
Legal Case #:7248

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
253271	1/9/2012	1/10/2012	1/10/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Cabela's		Cabela's	2200 W. Cabela's Pkwy	Gonzales	LA	70737		W 225-743-3400

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fires on safety release Concern:1007 Fired on Safe Release			
C				

1/26/12 Per note with rifle, fires when safety is taken off without touching the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	27093	G6935258	AE	3/10/2010 2:17:52 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	CABELA S INC/WAREHOUSE /		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, check over, test fire at no charge to restore confidence in rifle						

Repair/Replacement Cost	Repair/Replacement Date
47.40	1/26/2012

1/26/12 Per Ilion, could not duplicate concern. Will replace TPA, check over, test fire at no charge to restore confidence in rifle.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 243 WIN
	Date Code		AE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	BBL SCRATCHED
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Cabela's

2200 W. CABELA'S PARKWAY
GONZALES, LA 70737
PHONE (225)743.3400
FAX (225)644.2436

2248

INVOICE

241
AES/
4#
.01

TO Remington Attn: Service Dept.
14 Hoeffer Ave.
Hill, NY 13357

DATE	ORDER NO. JL
SHIP TO	
Repair	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS
QUANTITY	DESCRIPTION	UNIT PRICE	TOTAL	
1	Remington 700 ADL .243 Win			
	SN: G6935258			
	ID: 2554754			
	Serial: 00100053			
Fires when safety is taken off				
without touching the trigger.				
could not duplicate concern				
will replace TPA, check over				
test fire to restore confidence				
in rifle at n/c				
warranty				
and Day				

Number:

G6935258

JAN 16 2012

Model:

700

BY:



RE00253271





