

Remington Arms Co., Inc.
Product Service
Legal Case #:8069

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		10/19/2012					X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Sharon	Hall	5645 Silver Saddle Dr	Shepherd	MT	59079		H 406-281-7054

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD shot hole in truck	Cause:4079 Other - Unexamined		Unknown	
S	Concern:1008 Fired on Bolt Closing			
C				

10/19/12 Per call from Sharon, in Nov last year when putting a shell in the chamber the rifle fired and put a hole in the side of a truck. They also have a ADL that they thought was under recall. It actually has a bolt lock. They will send it for inspection also.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/	n/a	A6496662		8/30/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	C GREENBLATT HEMPSTEAD LI NY		N			

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/	n/a	6547174		
Date Purchased	Where Purchased	Accessories	Original Owner			
	CLARK WEBSTER CHESTERTOWN MD		N			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

10/19/12 Sending ARS for both rifles to come in for inspection. Will put on hold and contact Sharon afterward. The Mohawk is not included in the recall.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

ARS LABEL REQUEST FORM

DATE:	10/19/2012	Service Request #	SR00032419
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelics		
	email address:		

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	SHARON HALL 5645 SILVER SADDLE DR SHEPHERD, MT 59079 US SR00032419 Email:
RETURN ITEM TO:	ILN Arms Services



4XX596 OCT 19, 2012 ALL CURR USD 1 OF 1
 SVC GND COM ACT WT 10.0 LBS
 TRACKING# 124XX5969066560097
 REF 1: SR00032419
 REF 2:

HANDLING CHARGE 0.00		SVC T/P USD
SINGLE-PIECE PUB RATE CHRG:		
DY 0.00	COD 0.00	RS 0.50
DC 0.00	DGD 0.00	SD 0.00
AH 0.00	PR 0.00	SP 0.00
TGT PUB CHG 12.26	PUB+HANDLING	12.26

ATTN: Prod Serv #8069

ARS LABEL REQUEST FORM

DATE:	10/19/2012	Service Request #	SR00032418
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelcs		
	email address:		

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	SHARON HALL 5645 SILVER SADDLE DR SHEPHERD, MT 59079 US SR00032418 Email:
RETURN ITEM TO:	ILN Arms Services



1 OF 1

4XX596 OCT 19, 2012 ALL CURR USD
 SVC GND COM ACT WT 10.0 LBS
 TRACKING# 124XX5969066369885
 REF 1: SR00032418
 REF 2:

HANDLING CHARGE 0.00	SVC T/P USD
SINGLE-PIECE PUB RATE CHRG:	RS 0.50
DV 0.00	SD 0.00
DC 0.00	SP 0.00
AD 0.00	PUB+HANDLING 12.26
TOT PUB CHG 12.26	

ATTN: Prod Serv #8069