Remington Arms Co., Inc. Product Service Legal Case #:7337

(Case	\ln	lon	mai	110	L

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete 2/8/2012 1/27/2012 2/20/2012 1/26/2012 257877

Customer Information

Type Business First Name Last Name Street City Zip Contact Age Incident Anthony J. Chiodo 1704 Gross St. Conway 15027 H 724-869-9300

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PD Shot through house door, shattered the glass

Cause: 4038 Could Not Duplicate Concern Concern: 1008 Fired on Bolt Closing

Unknown

S FBC

C

1/27/12: Customer called in. He said that he was unloading rifle on 1/26/12 at his friend's camp house & had a FBC. He said he shot through the door, shattered the glass in the door & ended up with a hole in the deck. No injury. He wants us to pay for the repair of the door, df

Firearm Information

Mfg. Remington Type

Model/Ga.

SKU

Serial BbL

DOM

CF/BA

700/22-250 REM

n/a

261538 RP 11/1/1967

Date Purchased

Where Purchased

Accessories SCOPE BASE, BOTTOM HALF RINGS

Original Owner

Y

2/8/12: After your exam - please do BLM at n/c - goodwill gesture. df CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement

Reim. Date APV Cash Date APV

Kepair under BLM (a) n/c - goodwill gesture

Repair/Replacement Cost Repair/Replacement Date \$46

1/27/12: Mailing ARS & forms. Box order # 1301745. df 2/8/12: Customer sent the repair bill for the door. He doesn't expect to pay it. \$34.98. df 2/20/12: Per Ilion - Could not duplicate concern. Trigger Assm dirty, safety clip out of position causing safe to work too easily. Replace trigger plate assm, clean and test fire under bolt lock program at no charge. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		2/9/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 22-250 REM
	Date Code		RP
Barrel	Bore Plugged	False	
	Bulged	False]
	Fired	False	7

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7337&Type=Case

2/20/2012

1		7	<u> </u>
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	<u>_</u>
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	Faise	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning]
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Received	Bulged	False	
	Description]	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	—Select—	.004
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
.	Pull	Select	5.5#
Trigger	Altered	False	
1	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		SCOPE BASE, BOTTOM HALF RINGS

/

24 (1 R21/67 5,5° .004

7337

January 27, 2012

Anthony J. Chiodo 1704 Gross St. Conway, PA 15027 Phone: 724-869-9300

Ref: #7337, Model 700, Serial #261538

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure



could not duplicate concern T.A. dinty, salety clip out of ps. + she verles to easy. Hepince TPA, clean+ Test under BCP AT N/c pen Agreement.

260974

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Model Number:	Serial Number:						
Name: Anthon J Chiodo	Date of Purchase:						
Address (no PO Boxes):							
City: (1214124	State: P4 Zip: 15027						
	State: <u>PA</u> Zip: <u>15027</u>						
Phone (Daytime): 724-869-9300	Fax:						
E-mail Address:							
Please describe y	our problem:						
500 chara	cters left						
NOTE: Prior to shipping your firearm, corprovided and estima							
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.							
:: Pack your firearm for safety and to prevent handling. Preferate firearm box. (Note: Original box:: Remove all accessories from your firest firearm by either Utersponsible for dain during shipment, so you may elect to put	vent further damage in shipping and only, ship in a boxes may not be returned.) rearm to prevent loss or damage. PS or Parcel Post. Remington is not mage or loss						
Print	Reset						

Service Request

Remington Service PO Box 700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

Madison, NC 27025-0700 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number | Serial Number | Description 01/30/2012 Date of Request: SR00011168 261538 01/30/2012 Date Printed: Model 700 Center Fire Caliber: 22250 Customer: Destination: ANTHONY CHIODO Arms Services 1704 GROSS ST. 14 Hoefler Ave CONWAY, PA 15027 US Ilion, NY 13357 US Email: Email: Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION Product Service # 7337 Parts And Service Details

Type

Material

Description

Qty Needed

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

SA' ES TICKET NO 790

ECONOMY PLUMBING & HEATING CO., INC.

407 State Street

Baden, PA 15005 724-869-9310

:		4.		;; ;				æ.	3
Vame 7	ony		tiodo	Str	eet	124	- 8%	<u>2-2</u>	300
Lity			*	Sta	te				
Date /	<u>'-2</u>	フーノス			- 2				PRICE
	J	lex-	19-91	1455				d	1000
ſ	B	IK	NV	low				47	55 -
								_	19
							17		
	f		,).		\	7 (ر ا	37.7
	1, 3				,	. }	,		
		,		V.					
			,						
	,	,							
								,	
					:				
				."		· ·			
	114.% per	month charg	e is made or	n past due	invoices.	Annual p	ercentage	rate 18%)
Customa	er Signatu	ire .		~;					

Inclosed is The shell That went off
in my Rifle while closing the bott. Also
is the name and Adress of my neighbor
Jones sister
Isoq poport st
conver pa 15027. It was AT his camp
were this happened. He was there with me.
Also is A copy of the cost to depair
The screen door, Thank God no body got
there are Killed. I don't think that I
should have to pick up this bill!

Thmk you

Anthony J Chiodo

01-30-12 20 01 *33.00 # *1,98 # *34.98 # 696.3 15-04

ARS LABEL REQUEST FORM

DATE:	01/30/2012	Service Request #	SR00011168	
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL	

Business: Remington Service

PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

ANTHONY CHIODO 1704 GROSS ST. CONWAY, PA 15027 US SR00011168

Email:

RETURN ITEM TO:

ILN

Arms Services

AXX596 JAN 30, 2012 10.0 LBS #PK 1
SVC GNDCOM 124XX5969066984488 ALL CURRENCY USD
TRACKING# 124XX5969066984488
REF 1:SR00011168
REF 2:
HANDLING CHARGE 0.00 FRT: 3RD
SHIPMENT PUB RATE CHARGES:
DV 0.00 DGD 0.00 RS 0.50
DC 0.00 PR 0.00 ROD 0.00
AH 0.00 PR 0.00 PUB+HANDLING 9.69

ATTN: Product Service







