Remington Arms Co., Inc.
Product Service
Legal Case #:8371

Case Information RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 292992 12/14/2012 12/17/2012 12/17/2012 **Customer Information** Type **Business** First Name Last Name Street City Zip Age Contact Incident Wilkes 1063 Meadowlark Dr 29732 Faulk Rock Hill SC Incident Information Medical Repair Medical Claims Codes Est. Treatment Status PΙ PD Could Not Duplicate Cause:4038 Concern Unknown Fires when flipping safety to S Concern:1007 Fired on Safe Release fire 12/28/12 Per note on SR, fires when flipping safety to fire.cm Firearm Information Mfg. Type Model/Ga. SKU Serial Bbl. DOM CF/BA Remington 700/3006 SPRG 25773 C6469479 RJ 11/16/1989 Date Original Where Purchased Accessories Purchased Owner TWO PIECE BASE, BOTTOM HALF K MART U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

ENTERPRISES

Remington/700/CF/BA

RINGS

Settlement Release of Claims Release Date Reimbursement Cash Date Date APV APV

Per Ilion, offer to replace TPA, clean, test at 1/2 charge

Repair/Replacement Repair/Replacement
Cost Date

12/28/12 Per Ilion, could not duplicate concern. Trigger assm dirty. Can offer to replace TPA, clean, test at 1/2 charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/17/2012
Examination	Product Type		RF
	Action Type		A

	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		RJ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.015
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Puli	Select	6.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,BOTTOM HALF RINGS

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

R611/8 This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN. ,015

Service Request Number SR00037187

Serial Number / Description

C6469479

Model 700 RIFLE

WILKES FAULK

1063 MEADOWLARK DR ROCK HILL, SC 29732 US

Email:

Date of Request: 12/03/2012

Printed:

12/03/2012

Destination:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERV

Service Request Section CLAIMS RIFLE FIRES WHEN FLIPPING SAFETY TO FIRE.

Parts And Service Details

Material Type Description

Needed

could Not Eup. concern. T.A. durty, can offen to up. Tox, clean + rest 4t. 1/2 change

DEC 1 9 2012

BY:____

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax:

.00 .00

Grand Total:

\$.00





