Remington Arms Co., Inc.
Product Service
Legal Case #:7339

				Legal Case #./339						
Case Inform	nation			•						
RE#	Date Op		Date Opened(PS		Incid	ent Date	e P	re Lit	Lit	Obsolete
255720	1/27/20	012	1/30/2012	1/30/2012						
Customer In										
Type	Business	First Name	Last Name	Street	City	State	Zip	Age	C	Contact ⁻
Reporter	Gander Mt		Gander Mt	600 Galleria Dr	Johnstown	PA	15904		W 814	4-266-1777
Incident Inf	ormation		•							•
	Claims			Codes		Repair Est.		Medical reatmen	t	Medical Status
S on C	_	ried with safety		Altered Adjustments or Components Unexplained Discharge S thile being carried with sa			l	Jnknown		
				Third coming curried with the						
Firearm Info Mfg Reming Date Puro CONCERN	gton chased	CF/ Where P	urchased ORPORATION	Model/Ga. 700/7MM REM M Accessories TWO PIECE BAS	Orig	SKU 25803 inal Own U		Serial :6734374	Bbl. WM	
		- None Defined on - None Defin								
Settlement										
				Remington/700/CF/BA						
	Settlement	Re	lease of Claims	Release Date	Reimbur	sement	Cash Settlem		im. Da APV	te Cash Da APV
	eplace TPA, ci 1/2 normal c									
		Rep	air/Replacemen		t					
2/8/12 Per I	lion, trigger a	ssm set screws a	Cost altered. Trigger n	Date ot returning properly. Re	place TPA, o	lean, test	fire at 1	/2 norma	ıl cost.c	m
Examination	n[Remington/	CF/BA]								
			<u> </u>		7					
<u> </u>	Part		-Part	Code		DAVIC	C	omment	-	
		Examiner Exam Data				RAVIS /2012				
Evaminatio	.n	Exam Date			RF	12012				
Examinatio	ш	Product Typ			Kr A	<u></u>				
		Action Typ				AGLE				
<u> </u>		Assigned T	U		1.1	MULE				

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/30/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description		24" 7MM REM MAG
	Date Code		WM
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7339&Type=Case

2/8/2012

	Muzzle/Crown Condition	Slightly Worn; Functioning					
	Firing Pin	Slightly Worn; Functioning] .				
	Shroud	Slightly Worn; Functioning	<u></u>				
Bolt	Face	Slightly Worn; Functioning					
	Handle	Slightly Worn; Functioning					
	Stop	Slightly Worn; Functioning					
	Condition	Slightly Worn; Functioning					
Extractor	Cut Condition	Slightly Worn; Functioning					
	Ext/Eject Test	False					
	Block Condition	Select					
Locking	Lug Condition	Slightly Worn; Functioning					
	Notch Condition	Select	1				
	Exterior Condition	Slightly Worn; Not Functioning					
Overall	Stock Condition	Slightly Worn; Functioning					
	Fore End Condition	Select					
Receiver	Condition	Slightly Worn; Functioning					
Receiver	Bulged	False]				
	Description		M/700 SAFETY				
Safety	Function	Like new; Functioning]				
	Sub-Assembly	Non-ISS]				
	Lift	Select	.010				
Sear	Notch	Slightly Worn; Functioning					
	т	Test Fired	False				
Feeding Test	Tests	False					
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN				
Trigger	Pull	Select	1.5#				
	Altered	True	SET SCREWS ALTERED				
	Sub-Assembly	M/700 Non-Bolt Lock					
Non-Remington Components	Description		TWO PIECE BASE				



7339

Service Request Service Order # 2811

10, 10,

1992

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-01996 14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 01/17/2012

Phone: (800) 243-9700

RETURN SHIP TO:

JOHNSTOWN, PA 15904

Gander Mountain, FFL# 8-25-021-01-8B-01845 Attn: Gun Parts Dept. 600 GALLERIA DRIVE

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type: Rifle

Serial Number: c6734374

Model:

700

Cal/Ga.: .7mm

Cased?: □

DESCRIPTION OF ITEM RETURNED:

700 bdl

REASON FOR RETURN:

rifle discharged inadvertantly while being carried on safty, checktrigger/safty assembly

FEB 0 2 2012

ATTENTION VENDOR

Please contact me with any questions or concerns.

Paul Hornick or Larry Babal (814) 266-1777

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain

Attn: Cindy Kilbride

180 EAST 5 TH ST SUITE 1300 ST. PAUL, MN 55101-9941

> T. A. set screws altered Trig. Not returning properly. Replace TPA, CLEANT TEST Rine At 1/2 NORMAL COST.

CUSTONN

Quate

C6734374

Model:

700



Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00255720		Serial Number / Description C6734374 Model 700 Center Fire Caliber: 7 MM REM MAG			Date Re Estimat Date Pr	e Date:	01/23/2 01/30/2 02/08/2	012		
180 E 5TH SAINT PAU	OY KILBRII ST SUITE 1: JL, MN 55	300	Return To: GANDER MOUNTAIN 600 GALLERIA DRIVE JOHNSTOWN, PA 15904 US							
Please Circle On		TED Could No		г.,	D.+-					
VISA MO				Ex	p.Date					
Open Accou	iii: K	PO Number:								
Approval Signat	hire:				Date:					
Davtime Pho	ne: (Time to Ca	11:							
☐ If you des	ire any chans	ge, please use the reverse side for your comments and	mark this b	ox.						
		RODUCT SERVICE FOR INSPECTION MI MI M9 M9	23 - FORV 78 - TRIG 92 - fired o 94 - sear n	VARD TO PRO ADJ SCREWS out of battery ot returning pro	DDUCT SER S RESET, CA	VICE FOR NNOT RE	ADJUS'			
MFD of 8/92 W	ill offer to fi	Technician Cor t a new external adjustable T.P.A, clean, test for 1/2	normal cost	as good will g	esture.					
Material	Туре	ESTIMATE (note: C.O.D./Shipping and Handling Description	g Charges a Qty Needed	re NOT Includ Warranty	ded in this Q Qty From Inv	uote.) Price	Disc	Amount		
F306371B	Part	700 XMP EA TRIG ASSB RH BLACK (OS)	1	Billable	1	115.00	50	57.50		
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR		Billable	1	17.00	0	17.00		
4000116	Service	GR-LABOR	1	Warranty		.00	0	.00		
4000118	Service	GR-CLEAN	1	Billable	1	28.00		14.00		
4000119	Service	GR-TEST	1	Billable	. 1	23.00		11.50		
4000294	Service	GR-CHECK TPA	1	Warranty	1	.00	0	.00		

Sub Total: 100.00 Est Sales Tax: 3.74

Total: 163.74







