Remington Arms Co., Inc. Product Service

			Lega	l Case #:960	3					
Case Informat	ion									
RE# D	ate Opened	-		Date Close			t Date	Pre Lit	Lit	Obsolete
331121	2/16/2013	12/2/2013	3	12/17/2013	1	1/30/	2013			
Customer Info	rmation									
Type Busin	ess First Name	·-	Street	City	State	Zip	Age	C	ontac	t
Incident	Kent	Anderson 405 (Cannong Rd.	ate Kingspor	t TN 3	37660		H 423 rmgianders	Е	4720 hartertn.net
Incident Inform	nation									
Claims		Codes		Rep	air Est.	Me	dical T	reatment	Med	ical Status
ΡΙ										
PD	Cause:4038	Could Not Dupl	icate Co	ncern			** 1			
S FSR	Concern:10	07 Fired on Safe Re	elease				Unkn	own		
С										
12/2/13: Custo damage, no in		in. He stated the rif	le fired o	n safe release	e on 11/3	30/13.	He stat	ted it happe	ned 3	times - no
Firearm Inform	nation									
Mfg.		Туре	M	odel/Ga.	SK	U	Seri	al Bbl.	I	ОМ
Remington		CF/BA	700/	7MM REM MA	2738	35	G6883	669 WD		0/2009 9:23 PM
Date Purchased	Who	ere Purchased	Ac	cessories	Origi Own					
	MAHONE	EYS SPORTSMAN PARAD	IS		Y					
CONCERN: F	SR									
		- None Defined on - None Defined			***************************************				<u></u>	
			Reming	gton/700/CF/	BA					
Settlement	Release	of Claims	Release	Date :	Reimbu	rsem	ent Se	Cash ettlement	Rein Dat AP	e Date

Per Ilion -Repair @ n/c

> Repair/Replacement Repair/Replacement Cost Date \$50

12/5/13: Mailed ARS, letter, SR paperwork. Box order# 1570858. df 12/19/13: Could not duplicate concern as received. Mag box out of position when received. To restore confidence in rifle - will replace TA, check over & test at n/c. df

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9603&Type=... 1/14/2014

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/17/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		26" 7MM REM MAG
	Date Code		WD
	Bore Plugged	False	
Barrel	Bulged	Falsc	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	=
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	_
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	=
	Notch Condition	Select	=
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	7
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	==
	Pull	Select	3#
Trigger	Altered	False	SEALANT PRESANT
	Sub-Assembly	X-Mark Pro	JEN LEN II I I I I I I I I I I I I I I I I I

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9603&Type=... 1/14/2014

Quotation

Estimating Report

Parts and Repairs: P:/F:

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

Page: 1

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Remington disclaims all warranties concerning legality of a firearm's configuration under applicable state, county & local laws or

regulations. (Consumers a	are advised to check their local laws to determine w	decirci certai	ii iii cai iii iea	LUI CS AIC IAW	tul.		
Cu	ıstomer:			14	tem Return T	o:		
Cu		NDEDCON			KENT ANI			
		NDERSON INONGATE RD.			405 CANN			
		ORT. TN 37660 US			KINGSPO			3
	12111001	,				,	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
								ļ
Please Circle (One:		=					
-		OVER Card No.		Exp	.Date			
Open Acco	ount: R	OVER Card No PO Number:						
o po 1 1000	·-····							
Approval Sign	ature:				_ Date:			
Davtime Ph	one: () Time to Ca	all:	···.				
· ·		nge, please use the reverse side for your comments and						
<u> </u>			uns 00/					
Repair Numb	er	Serial Number / Description			Date Rece		12/16/201	
RE00331121		G6883669			Estimate l		12/17/201	
		Model 700 Center Fire Caliber: 7 MM REM MAG			Date Prin	ted:	1/14/2014	1
		Problem						
Reported	WARD TO	— 	und	DD TO BDO	DUOT CEDM	OF FOR	B ICDECT	TON
R014 - FOR	WARD IO	PRODUCT SERVICE FOR INSPECTION RO	14 - FORWA	ARD TO PROI	DUCI SERVI	CE FOR	IN2PEC1	IUN
		Technician Co	mments		····			
could not dupl	licate concer	n.magazine box was out of position when received to	restore confide	nce in rifle wi	Il replace trigg	ger		
		t fire at no charge						
-								
		ESTIMATE (note: C.O.D./Shipping and Handlin	g Charges are	NOT Includ				***************************************
Material	Type	Description	Qty	Warranty	Qty From Inv	Price	Disc	Amount
F306371B	Part	700 XMP EA TRIG ASSB RH BLACK (OS)	Needed 1	Warranty	1 Troil 111V	.00	0	.00
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)	1	Warranty	1	.00	0	.00
4000119	Service	GR-TEST	1	Warranty		.00	0	.00
4000119	Service	GR-1EST	1	warranty	T	.00	U	.00
					Sub ?	Total:		. 00
					Est S	ales Tax:	:	. 00
					Gran	d Total:		\$.00

emington. COPY

December 3, 2013

9603


Kent Anderson 405 Cannongate Rd. Kingsport, TN 37660 Phone: 423-247-4720

Ref # 9603, Model 700, Serial # G6883669

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory. This shipping label is for a UPS Hub or UPS Terminal or a UPS driver can scan the label and ship the package for you. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

> Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co, LLC Phone: 1-800-243-9700 ext 8686 Fax: 336-548-7872



BY:....



magi Box Out of Pos. when redo, to lestone confid. oden+ TOSTATINK

#260974

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number	-		Date of Request:	12/05/2013
SR00070089	G6883669		Date Printed:	12/05/2013
Customer:	Model 700 RIFLE	Destination:		
KENT ANDERSON		Arms Services		
405 CANNONGATE R	D.	14 Hoefler Ave	;	
KINGSPORT, TN 376	660 US	Ilion, NY 133	57 US	
Email:		Email:		
	e item(s) will be evaluated by our repontacted with an estimate before wor	pairman to determine if it is covered under our warranty rk is performed.	policy. If it is your fiream	n will be repaired and
Reason For Return M123 - FORWARD TO I	PRODUCT SERVICE FOR INS	SPECTION		
Service Request Section Product Service # 9603. dr	nf .			
1 roduct Service ii 7003. di				
Parts And Service Details				
Aaterial Type	Description	Qty Warranty	Price	Disc Amount
		Needed		
, •				
•				
			,	
(:n.<	when	Safety 15	Taken	074
FIRES		0:1-1	~ .	- , 3 ,
	1.1 3	different t	imes,	
7+ 0	did 3		1777	
_				
	•			
		•		
	This is a pre-estimate to repair, recor	ndition, or replace the item(s)	Sub Total:	.00
cing sent based on the conver	sation with our representative.		Est Sales Tax:	.00
			<u>.</u>	

\$.00

Grand Total:

Model Number:	Serial Number:	
700	G688366	9
Name:	Date of Purchase:	
KENT ANDERSON	2011	· · · · · · · · · · · · · · · · · · ·
Address (no PO Boxes):		
405 Canongate R	Pd	
City: Kingsport	State: 7N	Zip: 37660
Phone (Daytime): 423 - 247 - 4720	Fax:	
E-mail Address: armgiane	Verson @ Charter	ta.net
Please describe your problem:		
Going to shoot Gun Fired.		·
Next day Going	to Shoo	+ Cayote
to safety off	Gon Fir	ed went
to TRUCK Unl Safety off Br		+00K
500 characters left		

provided and estimated repair time:

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a

firearm box. (Note: Original boxes may not be returned.)

- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Chip your INCURED firearm by either UPC or Parcel Post, Remington is not responsible for damage or loss

during shipment, so you may elect to purchase insurance from your carrier

use our UPS label

ARS LABEL REQUEST FORM

DATE:	12/05/2013	Service Request #	SR00070089
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
Business:		Remington Service	

LABEL INFORMATION

					O 1.11	
MAIL LABEL 1	$\Gamma \cap \cdot$				_	
	O.	K	ENT ANI	DERSON	1	

405 CANNONGATE RD. KINGSPORT, TN 37660 US SR00070089

PO Box 700

Madison, NC 27025-0700 www.Remington.com

Email:

RETURN ITEM TO: ILN

Arms Services

4XX596 DEC 5, 2013 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5989068357101 1 0F 1

REF 1:SR00070089 REF 2:

SVC T/P USD RS 0.50 COD 0.00 DGD 0.00 PR 0.00 SD 0.00 SP 0.00

10.34

PUB + HANDLING

ATTN: Product Service



