Remington Arms Co., Inc.

				Product	t Service					
				Legal Ca	se #:874:	5				
Case Info	rmation			•						
RE # 306070	Date Opened 3/26/2013	D	ate Opened(P 3/27/2013	•	ate Close /27/2013		cident Date	Pre	Lit Lit	Obsolete
Customer	- Information									
Туре	Business	First Name	Last Name	Street	City	State 2	Zip Age		Contact	t
Reporter	Polk County Sheriff's Office	Keith Romp	Polk County She	103 East 1st Street	Des Moine	s IA 50			515-208-0 E @polkcou	0013 Intyiowa.gov
Incident I	nformation							•	0.	, -
Claims		C	Codes		Rep	oair Est.	Medical T	reatme	nt Med	lical Status
PI PD S FSR C SR# 4831	Cause:4038 Concern:10 7 - Service Reques	07 Fired	I Not Duplicat on Safe Relea	se	ng safety t	to fire". df		own		
Firearm I	nformation									
Mfg	g.	Тур	e	Model/	Ga.	SKU	Serial	Bbl.	D	OM
Remin	gton	CF/BA		40X/308 WIN		27225	S672166	4 RF	F 11/30/2011 12:49:56 PM	
Dat Purch:	· · · · · · · · · · · · · · · · · · ·	Where Purchased POLICE DEPT / TACTICAL UNIT			ories	Original Owner				
	POLICI					U				
CONCER	N: FSR									
_	ion Information - Number of the Information of the Information									
				Remington/	/40X/CF/	ВА				.
Sett	tlement R	elease of	Claims	Release l	Date	Reimbu	rsement Se	Cash ttlement	Reim Date Al	- Date
Dor Ilian	Donlars TA									

Per Ilion - Replace TA & test fire @ n/c

Repair/Replacement Repair/Replacement Cost Date

\$50

3/28/13: Per Ilion - Could not duplicate concern. Safe works hard. Check over, replace TA & test fire @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
Examination	Exam Date		3/27/2013	
LAGIIIIIation	Product Type		RF	

	Action Type	1	A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description		24" 308 WIN HB
	Date Code		RF
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	7
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
G C .	Description		STANDARD SAFETY
Safety	Function	Slightly Worn; Functioning	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	HARD OFF SAFETY
T-:	Pull	Select	3#
Trigger	Altered	False	40X TRIG ASSM SEALANT PRESANT
	Sub-Assembly	M/700 Non-Bolt Lock	

Service Request

Remington Service PO Box 700

Date of Request:

Date Printed: 03/19/2013

03/19/2013

Medison, NC 27025-0700

www.Remington.com

Parts and Repairs: P:800-243-9700/F:336-548-7801 This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

,012

SR00048317

Service Request Number | Serial Number | Description

\$6721664

Model 4 RIFLE Caliber: 308

Customer:

Polk County Sheriff's Office Sgt. Keith Romp

103 E. 1st Street

Des Moines, IA 50309 US

PH 575 248-6074

Destination: 14 Hoefler Ave

Ilion, NY 13357 US

Email: Keith.Romp@polkcountyiowe.gov -Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M307 - BROKEN TRIGGER/TRIGGER GUARD M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section

RIFLE FIRED WHILE MOVING SAFETY TO FIRE.

Parts And Service Details Type

Material

Description

Qty Needed

Warranty

Price Disc Amount

環S6721664

Model:



THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

could prot dup concerns safe works hard check over hy. TPA. + TOST Rine AT N/C

> Sub Total: Est Sales Tax:

. 00

Grand Total:

\$.00







