Remington Arms Co., Inc. **Product Service** Legal Case #:8704

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 304251 3/11/2013 3/15/2013 3/15/2013 Х

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact H 816-750-4575 23009 Northeast 100th St. Liberty MO 64068 Incident Steven Sage E stevensage@hotmail.com

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

PD

Cause:4013 Broken or Missing Parts

Unknown Concern:1007 Fired on Safe Release

S FSR

SR# 44114 - Service Request Section: States rifle will fire when safety is taken off. df

Firearm Information

Model/Ga. Mfg. Type SKU Serial Bbl. DOM 710/7MM REM 6/13/2005 3:11:01 CF/BA 27412 71230048 PZ Remington MA AM Original Date Where Purchased Accessories Purchased Owner

CABELAS SCOPE BASE N INC/WAREHOUSE

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Reim. Date Cash Date Cash Settlement Release of Claims Release Date Reimbursement Settlement

Per Ilion - Repair

@ n/c

Repair/Replacement Repair/Replacement Cost Date \$41

3/18/13: Per Ilion - Insert housing is broken. Check over completely, replace TA, clean & test at n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		3/15/2013
	Product Type		RF
	Action Type		Α
	Assigned To		S.NICHOLS

PrintDisplay Page 2 of 2

Cause	4013	Broken or Missing Parts	INSERT HOUSING IS CRACKED
Barrel	Description		24" 7MM REM MAG
	Date Code		PZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning] .
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning]
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select]
Magazine	Condition	Select	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Not Functioning]
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	16913	False	
Trigger	Condition	Slightly Worn; Not Functioning	INSERT HOUSING BROKEN/CRACKED
	Pull	Select	5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	Other Remington	

Service Request

Remington Service PO Box 700

Date of Request: 02 04 2013

Date Printed: 02 04 2013

Madison, NC 27025-0700

Parts and Repairs: P:\$00-243-9700 F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number Serial Number / Description

SR00044114

71230048

Model 10

Customer: STEVEN SAGE

23009 NORTHEAST 100TH STREET

LIBERTY, MO 64068 US

Destination: Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email: stevensage Thotmail.com

Email:

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section

states title will fire when safety is taken off

Parts And Service Details Material

Description

Warranty

Price Disc Amount

we didn't buy the full from reminstern or a dealer and we will pay for the repairs to make the gun

型71230048

INSERT HOUSING IS BROKEN TPA, ELEAN + TOST AT N/C # 230145

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00









