

| | | | |
|--------------|------------------------|--------------------------------|-----------------------------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 1/9/2014 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | S.NICHOLS |
| Cause | 4015 | Improper Maintenance | |
| Barrel | Description | | 22" 3006 SPRG |
| | Date Code | | LO |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Not Functioning | SLUGGISH |
| Extractor | Condition | Slightly Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Slightly Worn; Not Functioning | |
| | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | | BOLT LOCK SAFETY |
| | Function | Like new; Functioning | |
| Sear | Lift | ---Select--- | .005 |
| | Notch | Slightly Worn; Functioning | |
| | Tests | Test Fired | False |
| Feeding Test | | False | |
| Trigger | Condition | Slightly Worn; Not Functioning | VERY DIRTY WILL FOLLOW DOWN |
| | Pull | ---Select--- | 3# |
| | Altered | False | SEALANT PRESANT |
| | Sub-Assembly | M/700 Bolt Lock | |

Remington®

COPY

22
102/7
34
.005

December 2, 2013

9608

Dennis Crabtree
345 Pleasant Valley Ln.
Oneida, TN 37841
Phone: 423-286-6326

Ref # 9608, Model 700, Serial # A6422394

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory. This shipping label is for a UPS Hub or UPS Terminal or a UPS driver can scan the label and ship the package for you. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co, LLC
Phone: 1-800-243-9700 ext 8686
Fax: 336-548-7872

Serial
Number:

A6422394

Model: 700



RE00333110

RECEIVED
JAN 10 2014

BY:.....

Remington Arms Company, LLC • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

| Service Request Number | Serial Number / Description | Date of Request: 12/05/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|-------------------------------------|------------------------------------|------------|---------------------------|-----------------------|------|--------|--|--|--|--|--|----------|------|-------------|------------|----------|-------|------|--------|--|--|--|--|--|--|--|--|--|--|
| SR00070207 | A6422394 | Date Printed: 12/05/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | Model 700 Center Fire Caliber: 3006 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Customer: | | Destination: | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| DENNIS CRABTREE | | Arms Services | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 345 PLEASANT VALLEY LN. | | 14 Hoefler Ave | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ONEIDA, TN 37841 US | | Ilion, NY 13357 US | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Email: | | Email: | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p>Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p>Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p>Service Request Section Product Service # 9608. dmf</p> | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th colspan="2">Parts And Service Details</th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> </tr> <tr> <th>Material</th> <th>Type</th> <th>Description</th> <th>Qty Needed</th> <th>Warranty</th> <th>Price</th> <th>Disc</th> <th>Amount</th> <th></th> </tr> </thead> <tbody> <tr> <td colspan="9" style="height: 300px;"> </td> </tr> </tbody> </table> | | | | Parts And Service Details | | | | | | | | | Material | Type | Description | Qty Needed | Warranty | Price | Disc | Amount | | | | | | | | | | |
| Parts And Service Details | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Material | Type | Description | Qty Needed | Warranty | Price | Disc | Amount | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| <p>THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.</p> | | | | | Sub Total: | | .00 | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | Est Sales Tax: | | .00 | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | Grand Total: | | \$.00 | | | | | | | | | | | | | | | | | | | | | | | |

ARS LABEL REQUEST FORM

| | |
|-------------------------|----------------------------------|
| DATE: 12/05/2013 | Service Request # SR00070207 |
| QUANTITY: 1 | WEIGHT PER PACKAGE: 10 LBS |
| REQUESTED BY: fulcherdm | email address: I WILL MAIL LABEL |

| | |
|------------------|---|
| Business: | Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com |
|------------------|---|

LABEL INFORMATION

| | |
|------------------------|---|
| MAIL LABEL TO: | DENNIS CRABTREE 345 PLEASANT VALLEY LN. ONEIDA, TN 37841 US SR00070207 Email: |
| RETURN ITEM TO: | ILN Arms Services |



4XX596 DEC 6, 2013 ALL CURR USD 1 OF 1
 SVC GNDCOM ACT WT 10.0 LBS
 TRACKING# 1Z4XX5969086526967
 REF 1:SR00070207
 REF 2:

| | | | |
|-----------------------------|--------------|-------------|--|
| HANDLING CHARGE 0.00 | | SVC T/P USD | |
| SINGLE-PIECE PUB RATE CHRG: | | | |
| DV 0.00 | COD 0.00 | RS 0.50 | |
| DC 0.00 | DGD 0.00 | SD 0.00 | |
| AH 0.00 | PR 0.00 | SP 0.00 | |
| TOT PUB CHG 11.01 | PUB+HANDLING | 11.01 | |

| | |
|------------------------------|--|
| ATTN: Product Service | |
|------------------------------|--|









