PrintDisplay Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:8934

			Legal Case #:693	14					
Case Information	1								
RE#	Date Opened	Date Open	ed(PS) Date Clos	ed Incid	ent Date	Pro	Lit	Lit	Obsolete
313119	6/11/2013	5/22/20	13 6/12/201	3					X
Customer Inform	ation								
Type Busin	ness First Nam	ie Last Name	Street	City	State	Zip	Age		Contact
Incident	Ed	Dunivant	6706 Sycamore Woods	Dr. Louisvi	lle KY	40241			2-425-8281 2-386-4933*
Incident Informa	tion								
Claims		Codes	Rep	air Est. N	tedical T	reatment		Medi	cal Status
Pl									
PD		3 Broken or Mis	•		Unkno	own			
S FSR C	Concern:10	007 Fired on Safe	Release		07				
5/22/13: Ed Duni personal injury. o		e stated the muzzle	loader will fire on safe rel	ease consistently	He said t	here was	no pro	perty d	amage or
Firearm Informat	tion								
Mfg.		Type	Model/Ga.	SKU		Seria		Bbl.	DOM
Remingtor		ML/BA	700ML/50 CAL	27572		ML207	637	BS	1/30/1998
Date Purcha		re Purchased	Accessories	Original O	wner				
CONCERN: FSF		R BROS INC	TWO PIECE BASE	Y					
Ammunition Info	ormation - None I	Defined							
Other Products In	nformation - Non	e Defined							
Settlement									
			Remington/700ML/M	IL/BA					
Settlemen		ase of Claims	Release Date	Reimburseme	nt T	Cash Ilement		n. Date IPV	Cash Date APV
Per Ilion - Rep clean @ n	/c								
	Repai	r/Replacement	Repair/Replacement						
		Cost \$34	Date						
5/22/12, Mailed	ADC latter CD m	•••	Day and 1506127	#6 6 / 19 / 12 . Don II	ion TA	ot	alton		anton in
	TA, check over &		mer. Box order# 1506137.	Q1 6/18/13: PCF11	ion - TA	sei screws	ancie	su, com	ector is
Examination[Rea	mington/ML/BA]								
Par		Sub-Part	Code			Con	nmeni		
1 41		aminer		B TE	AVIS	CVII		<u> </u>	
))=== (am Date			2013			-	
Examination		oduct Type	=	RF					
	<u> </u>	tion Tomo	==	<u> </u>					

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date]	6/12/2013
Examination	Product Type		RF
	Action Type]	A
	Assigned To		S.NICHOLS
Cause	4013	Broken or Missing Parts	CONNECTOR IS BROKEN
	Description		24" 50 CAL ML
	Date Code]	BS
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		_

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8934&Type=Case

6/18/2013

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Select	AFT MKT
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Select	
	Handle	Slightly Worn; Functioning	
	Stop	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Meceivei	Bulged	False	
Safety	Description		STANDARD SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	10515	False	
	Condition	Slightly Worn; Not Functioning	CONNECTOR IS BROKEN
Trigger	Pull	Select	N/A
Tilggei	Altered	True	SET SCREWS ALTERED SEALANT MISSING
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Remington.

May 22, 2013

8934

Ed Dunivant 6706 Sycamore Woods Dr. Louisville, KY 40241 Phone: 502-386-4933

Ref # 8934, Model 700ML, Serial # ML207637

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co, LLC
Phone: 336-548-8686

Fax: 336-548-7883 or 7872

Ŋ:	EC. NUL	Œ	IJ	W I	
	JUN	1	9	2013	

BY:

Serial Number:	L2	07	63	37		
		70				
1						
,	R	EQ	003	31:	31	19

T.A. set screws Alt.
connector is Brusen.
Ap. TAA, chiell overetchan
At M/C

#230145

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number	Serial Number / Description			Date of Request:	05/23/2013
SR00053583	ML207637			Date Printed:	
	Model 700ML RIFLE Caliber: 50				
Customer: ED DUNIVANT			nation: Arms Services		
6706 SYCAMORE WO	OODS DR.		14 Hoefler Ave		
LOUISVILLE, KY 40		1	llion, NY 13357	US	
Email:		I	Email:		
Your request for service on the returned. If not, you will be co	e item(s) will be evaluated by our repairman to determ ontacted with an estimate before work is performed.	nine if it is covered un	der our warranty pol	icy. If it is your firearm	will be repaired and
Reason For Return M123 - FORWARD TO I	PRODUCT SERVICE FOR INSPECTION				-
Service Request Section Product Service # 8934. Co	ustomer stated fired on safe release. dmf				
	en de la companya de	الفاريخ المحتصين	en en som en		
Parts And Service Details Material Type	Description	Qty Needed	Warranty	Price	Disc Amount
		,		,	
			عادي عادي المارية	<i>ምምለ</i> ያታጉ	
			JUN 1	3 2013	
			ВҮ:		
	-				
THIS IS NOT AN INVOICE. Theing sent based on the conver	This is a pre-estimate to repair, recondition, or replace	the item(s)		Sub Total: Est Sales Tax:	.00

\$.00

Grand Total:

ARS LABEL REQUEST FORM

Business:	Remington Service PO Box 700
	Madison, NC 27025-0700 www.Remington.com
	www.kemington.com

LABEL INFORMATION

	LADEL IN CINIMATION	
MAIL LABEL TO:	ED DUNIVANT 6706 SYCAMORE WOODS DR. LOUISVILLE, KY 40241 US SR00053583 Email:	
RETURN ITEM TO:	ILN Arms Services	
		<u>.</u>



4XX596 MAY 23, 2013 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS #PK 1 10.0 LB

ATTN: Product Service









