

Microsoft Access

File Edit View Records Window Help

Customer Service Data Entry

File Number: 9168 Arms Service number: 9702313

Last Name: HEBERLIN First Name: GS SPORT SHOP

Street: OLD RTE 170 City: PROMPTON

State: PA Zip: 18456 Home Ph:

Work Ph: 717-253-1801 Product Type: F A T O

Type Concern: S P P D P S C Concern Code: 1028

Concern: FIRED WITH SAFE ON

Cause Code: 4001 Cause: IMPROPER MAINTENANCE

Assigned To: KAST Classification: UNJ UNJ UNC UND J

Settlement Detail: REPAIR SPCL PRICE Settlement Amount: \$0.00

Date Opened Rem: 1/27/97 Date Opened by P/S: 2/19/97 Caliber: 270

Date of Incident: Date Closed: 2/19/97 Bullet Weight:

Date to Analysis: Date from Analysis: Manufacturer: REM

Model: 700 Serial: C6595891 Date Code: DM Date Mfgd: 9/1/92

RAMAC: 700 Litigation: PreLitigation: Obsolete:

Custody: Comments: WOULD NOT FIRE WITH SAFE ON - TRIGGER & HOUSING RUSTED

Time of Modification: 11:21:34 AM Date of Modification: 2/19/97

Form View FLTR CAPS NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 97-02313

INITIAL CUSTOMER ORDER NO.

CUSTOM SHOP

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/20/97

01/27/97

DM 9-92

C6595891

700 270

CAMO/LH

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

HEBERLINGS SPORT SHOP
OLD RTE 170
PO BOX 73 RIVER ROAD
PROMPTON

PA 18456

HEBERLINGS SPORT SHOP
OLD RTE 170
PO BOX 73 RIVER ROAD
PROMPTON

PA

18456

CUST NO:005519 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Fires with safe on

MAIN FAULT

Gun could not be made to fire with safe on. Trigger pull is hard due to rust inside of trig. housing and on trigger. Exchange trig. Assy at a special price strictly as a gesture of good will.

PARTS

COMMENTS

Trig pull measured 8 LBS as Rec'd.

Trig Assy.

See owners manual for proper care and maintenance.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6025 REV 1196

PS 34613



tel: (717) 253-1801

P.O. Box 73
River Road
Prompton, Pa. 18456

Remington Arms
14 Hoefler Ave
Shon, NY 13357

Dear Sirs:

Please repair the enclosed rifle. It
fires when the safety is on.

Thank you.
Heberling's