

Customer Service Data Entry					
File Number:	9160		Arms Service number:	9704292	
Last Name:	JONES		First Name:	PHIL	
Street:	618 N MAPLE ST		City:	EMPORIUM	
State:	PA	Zip:	15834	Home Ph:	
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	P I P S C	Concern Code:	1029	
Concern:	FIRED WITH SAFE ON				
Cause Code:	4033	Cause:	NO FAULT FOUND		
Assigned To:	KAST	Classification:	UNJ	UNJ UNC UND J	
Settlement Detail:	REPAIR SPCL PRICE		Settlement Amount:	\$0.00	
Date Opened Rem:	2/17/97	Date Opened by P/S:	2/18/97	Caliber:	270
Date of Incident:		Date Closed:	2/18/97	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	6789036	Date Code:	RY
Date Mfgd:	11/1/74	BAMAC:	700	Litigation:	☐
PreLitigation:	☐	Obsolete:	☐	Custody:	
Comments:	sear gummed up and sticking in housing				
Time of Modification:	1:32:47 PM	Date of Modification:	2/18/97		

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORD

R 97-04282

INITIAL CUSTOMER ORDER NO.

PRODUCT SERVICE

JJM

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
02/11/97	02/17/97	RY 11-74	6799036		700 270 BDL

ACCESSORIES SCOPE BASE W/STUDS

FROM:

SHIP TO:

JONES, PHIL M
618 N MAPLE ST
EMPORIUM

PA 15834

JONES, PHIL M
618 N MAPLE ST
EMPORIUM

PA
15834

CUST NO: 041972 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

38.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Unable to duplicate customer concern as recd. Bear gun mated and, sticking in housing. Took trigger assy apart and no other fault found. Exchange trigger assy at a special price strictly as a gesture of good will.

PARTS

COMMENTS

Trigger Assy

Trigger pull 3 3/4 to 4 LBS as recd.

Magazine box installed up side down.

Bolt stop sticks as recd.

Sear engagement OK

See owners manual for proper care and maintenance.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

SERVICE COPY

RD6925 REV. 11/96

618 Maple St
Emporium, Pa 15834

Mrs Celeen Lynch
14 Haepler
Elion, New York 13357

Dear Mrs Lynch:

It was a pleasure to talk to you the other day. I was somewhat surprised to find so much interest in guns from a woman.

The gun I am sending is a 700 Remington rifle and the owner has told me it has fired when the safe was on. I fired it ten times without this happening but the man insisted in sending it to Elion for a complete check up. Please do this work and return it to me with covering letter.

I hope the ~~twelve gauge~~ side by side shot gun meets the Remington requirements.

Sincerely,

Phil M. Jones