

File Number	395R	Arms Service number	9721843
Last Name	JUNBO SPORTS	City	TALLAHASSEE
Street	3246 CAPITAL CIRCLE NE	Home Ph	
State	FL	Zip	32308
Work Ph	850 2984477	Product Type	F A T O
Type Concern	S	PI PD P S C	Concert Code
Concern	FIRED ON SAFE RELEASE		
Cause Code	4039	Cause	NO FAULT FOUND
Assigned To	KAST	Classification	UNC
Settlement Detail	REPAIR N/C	UNJ UNC UNJ J	Settlement Amount
Date Opened Rem	12/12/97	Date Opened by FIS	12/22/97
Date of Incident		Date Closed	12/22/97
Date to Analyze		Date from Analysis	
Model	700	Serial	E6305071
MANAC	700	Litigation	
Custody		Comments	
		Pred Litigation	
		Caliber	243
		Bullet Weight	
		Manufacturer	REM
		Date Mfgd	8/1/96
		Obsolate	
Time of Modification	3:36:25 PM	Date of Modification	12/22/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-21843

INITIAL JJM	CUSTOMER ORDER NO.				
DATE RECEIVED 12/10/97	DATE OPENED 12/12/97	DATE CODE WQ 8-96	SERIAL NUMBER E6305071	NEW SERIAL NUMBER	MODEL AND GRADE 700 243 BDL
ACCESSORIES W/STUDS					

FROM:

JUMBO SPORTS
3240 CAPITAL CIRCLE NE
TALLAHASSEE FL 32308

SHIP TO:

JUMBO SPORTS
3240 CAPITAL CIRCLE NE
TALLAHASSEE FL 32308

ACCOUNT NUMBER	ACCOUNT NUMBER NC	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	-------------------	--------------------------------	------------	-----------	-------------------

GUN CONDITION	Prod. Sem.	REPAIR CHARGE
☒ NEW		EXCISE
☐ LIGHTLY WORN		TAX
☐ WORN		INSURANCE
☐ VERY WORN		UPS
☐ UNREPAIRABLE		PARCEL POST
☐ MARRED		TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5				F4
WOOD			D3			F5
METAL						

MAIN FAULT

Unable to make gun fire except with safe off and trigger pulled as rec'd.

Exchange trig assy. to restore customer confidence in the rifle. at W/C strictly as a gesture of good will.

PARTS

COMMENTS

trig pull 3 1/2 lbs as rec'd

sem engagement in spec

REPAIRMAN WJS	PROOF	CLEAN	TEST	TARGET	PATTERN
DATE	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 7-97

JUMBO SPORTS
3240 CAPITAL CIRCLE NE
TALLAHASSEE, FL 32308

SERVICE INSTALL	☐ PICKUP ☐ DELIVERY	REPAIR IN ☐ HOME ☐ SHOP	DATE ORDERED / /
--------------------	--	--	---------------------

MAKE	MODEL	SERIAL NO.
Remington	700 BDL	E6305071
WARRANTY	SERVICE REQUESTED	DATE PROMISED
CONTRACT	Fires w/o Trigger	/ /
ESTIMATE	Being Pulled / Does not Eject Properly	

[illegible]

~~and~~ Move performance and charges, as being satisfactory and acknowledge that equipment has been left in good condition.

TECHNICIAN'S SIGNATURE

THANK YOU Service Order