

File Number:	9974	Arms Service number:	19722579
List Name:	REESE SUPPLY CO	First Name:	
Street:	RD 1 BOX 136	City:	SMITHFIELD
State:	PA	Zip:	15478
Home Ph:		Home Ph:	
Work Ph:		Product Type:	F A T O
Type Concern:	S FI PD P S C	Concern Code:	1007
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4039	Cause:	NO FAULT FOUND
Assigned To:	KAST	Classification:	UNC UNJ UNC UNJ J
Settlement Details:	REPAIR N/C	Settlement Amount:	50.00
Date Opened Rem:	12/19/97	Date Opened by FIS:	12/29/97
Date of Incident:		Date Closed:	12/30/97
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	C6843573
RAMAC:	700	Litigation:	<input type="checkbox"/>
Custody:		Comments:	
		ProLitigation:	<input type="checkbox"/>
		Obscure:	<input type="checkbox"/>
		Manufacturer:	REM
		Date Mfg:	1/1/94
		Bullet Weight:	
		Caliber:	243
Time of Modification:	8:38:57 AM	Date of Modification:	12/30/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER R 97-22579

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED 12/17/97	DATE OPENED 12/19/97	DATE CODE BO 1-94	SERIAL NUMBER C6843573	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	ADL
ACCESSORIES W/STUDS			SCOPE BASE			

FROM:

REESE SUPPLY CO
RD 1 BOX 136
SMITHFIELD PA 15478

SHIP TO:

REESE SUPPLY CO
RD 1 BOX 136
SMITHFIELD PA 15478

CUST NO: 005925 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED 12-29-97	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------------------	------------

- GUN CONDITION
- NEW
 - LIGHTLY WORN
 - WORN
 - VERY WORN
 - UNREPAIRABLE
 - MARRED

REPAIR CHARGE
EXCISE
TAX
INSURANCE
UPS
PARCEL POST
TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						F1
BOLT ASSY.		B3				F2
BARREL ASSY.						F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			I C2			

Customer states that gun will fire when taken off safe

MAIN FAULT *Unable to duplicate customer concern as recd. Exchange trigger assy at N/C due to age and condition and to restore customer confidence in the rifle*

PARTS	COMMENTS
	<i>Trig pull 3#s as recd. see engagement in spec. Small amount of rust on trigger and firing pin. See owners manual for proper care and maintenance.</i>

REPAIRMAN <i>KRS</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

