

Customer Service Data Entry			
FIND: dal'on		[Icons]	
File Number: 9146	Arms Service number: 9702562		
Last Name: T&T JUNS	First Name: & SUPPLIES		
Street: 2250 THOUSAND OAKS	City: SAN ANTONIO		
State: TX	Zip: 78232	Home Ph:	
Work Ph: 210-495-0588	Product Type: F	F A T O	
Type Concern: S	P D P S C	Concern Code: 1008	
Concern: FIRED ON BOLT CLOSING			
Cause Code: 4039	Cause: NO FAULT FOUND		
Assigned To: KASR	Classification: UNC	UNJ UNC UND J	
Settlement Detail: REPAIR N/C	Settlement Amount: \$0.00		
Date Opened Rem: 1/29/97	Date Opened by P/S: 2/17/97	Caliber: 22-250	
Date of Incident:	Date Closed: 2/17/97	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer: REM	
Model: 700	Serial: D6830805	Date Code: RD	Date Mfgd: 11/1/94
RAMAC: 700	Litigation: ☐	PreLitigation: ☐	Obsolete: ☐
Custody:	Comments:		
Time of Modification: 12:56:49 PM	Date of Modification: 2/17/97		

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Product Service*ORDER
R 97-02562

INITIAL CUSTOMER ORDER NO.

JIM
DATE RECEIVED 01/23/97 DATE OPENED 01/29/97 DATE CODE RQ 11-94 SERIAL NUMBER D6030805 NEW SERIAL NUMBER MODEL AND GRADE 700 22-250 BDL
ACCESSORIES W/STUDS SCOPE BASE

FROM:

T&T GUNS & SUPPLIES
2250 THOUSAND OAKS
SAN ANTONIO

TX 78232

SHIP TO:

T&T GUNS & SUPPLIES
2250 THOUSAND OAKS
SAN ANTONIO

TX
78232

CUST NO: 135345 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE	A1	<i>Misfired when forcing bolt down</i>				
TRIGGER GROUP						
BOLT ASSY.				E2		F2
BARREL ASSY.		B1		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL						

MAIN FAULT

The only way that the gun could be made to fire as needed was with the safe off and the trigger pulled. Took trig. assy. apart and still no fault found. Exchange trig. assy. at N/C due to age and condition.

PARTS

Trig. Assy.

COMMENTS

*Trig pull 4 to 4 3/4 as needed.**Gear engagement in spec.**Face of Bolt should filed as needed. OK to use.**Deburr ejector plunger hole*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11/96

Att -

Customer is having problems
Chambering rounds - Also
Said that it missed fired
when he was forcing bolt
down - please Repair
and Return -

Thanks

Heath Thorne

T AND T GUNS AND SUPPLIES
2250 THOUSAND OAKS
SAN ANTONIO, TEXAS
78232

HEATH

Indoor
Range

Gunsmithing

Custom
Work

100% Financing
Available

BRUCE

T & T GUNS AND SUPPLIES

2250 Thousand Oaks
San Antonio, Texas
78232

(210) 495-0588 Fax 495-0190

DIANNE

HOPPE