

TEST OBSERVATIONS: (Continued)

4. Visual inspection was made and on file in lab. These are not included with report since later guns are to be reviewed for visual appearances.
5. Gun No. 8 Serial No. 6658215 was fired in a 500 round endurance test. Twenty-nine (29) don't extract malfunctions were recorded, all taking place after 380 fired rounds.

AAH:bd  
Measurement/Test Lab  
Ilion Research Division