


VISUAL INSPECTION

A-18

3" Crack in tip.



Heavy Scratches
on some stocks.

