



The Strands had
to be Cut Off



Gap between
Recoil Pads
and Stocks.



Some large Knots
on the Stocks.

