

... NO GUN EXAMINATION REPORT NUMBER: 594 MODEL: M-700 ADL
 SERIAL CONDITION: GOOD R #: 32631
 INSIDE WORK: TWO SCOPE SCREWS REMOVED DATE: 12-17-81
 FROM: JOSEPH MORRIS
RTN 3 BOX 37A
POUGHKEEPSIE, NY, 2313
 GUN TYPE: NOT KNOWN GUN #: B6265392
 & CONDITION: _____ CODE: PA-11-80
 RECOIL: REP DISP.: 52 TEST: 53 GA./CAL.: 243
 FEEDING: OK CHECKED BY: M-HARDY
 EJECTOR OPENING: OK APPROVED: 90H 1/19/82
 EJECTOR SHOULDERS: OK APPROVED: 90H 1/19/82
 TRIGGER: OK APPROVED: 90H 1/19/82
 TEST: _____ APPROVED: 90H 1/19/82
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 90H 1/19/82
SLIGHT SCRATCHES ON WOOD

 COMPLAINT: FIRE WHEN SAFE IS RELEASED

 INCIDENT: _____

 COMMENTS: Unable to duplicate customer complaint.
- Trigger pull 3 1/2 #
- Horizontal S&W Engagement .018
- Vertical S&W lift - Full Safe .0095

