

RECEIVING AND ESTIMATING REPORT

DATE RECEIVED 12-1-82 ESTIMATED _____

ORDER **R27018**

DATE OPENED 12-1-82 VIA UPS

MODEL AND GRADE 300 P.M. 30-06 SERIAL NO. 6280288

calitudo w/sage mts bottom hole DATE CODE DS 9-69

FROM:

*Lee Courcy
3571 Heim Dr.
Sterling Hgts MI 48077*

REPAIR CHARGE _____

INS. _____

UPS _____

PARCEL POST _____

TOTAL \$ _____

GUN CONDITION: (NEW) (SLIGHTLY WORN) (VERY WORN) (MISUSED) (QUOTE)

CUSTOMER'S COMPLAINT _____

MAIN FAULT _____

DEFECT
CODE

PARTS _____

FOR COMPUTER REFER. ONLY

PROOF _____

(CLEAN) (TEST) (TARGET) _____