

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-14996

INITIAL CUSTOMER ORDER NO.

CALL TAG, DENNIS SANITA

FDC

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

05/04/94

05/04/94

EN 10/93

S6245097

700 338WIN.

HAG SS

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

BOSCO & MARTINS FISH & GUN

HWY 63 S RT 3

BOX 72

LANCASTER

MO 63548

BOSCO & MARTINS FISH & GUN

HWY 63 S RT 3

BOX 72

LANCASTER

MO 63548

CUST NO 024463 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER NC

059001

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY

B3

BARREL ASSY

B4

REC. ASSY

B5

WOOD

C1

METAL

C2

MAIN FAULT

Upon receipt we were made to understand the customer desired a new 5th time it is about the 1st time found. Rifle only 10/93 by post received 4th time off

PARTS 013

COMMENTS

When moving safety handle & cock, the pump gun assembly was more slightly the in normal condition. However, we can minimize by changing pump gun assembly to prevent a tighter fit had fit.

Let pump gun assembly, adjust to tight fit, following trigger assembly complete to help restore pump in life.

Rush must ship by
Monday 5/9/94

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94