

RECEIVING AND ESTIMATING REPORT
BARBER - Kinzer PPS GAL RE0000661

ORDER
R 94-14539

ATTN: DENNIS SANITA

CUSTOMER ORDER NO.

FPS

DATE RECEIVED 04/28/94	DATE OPENED 04/29/94	DATE CODE OK 7-90	SERIAL NUMBER C6567884	NEW SERIAL NUMBER	MODEL AND GRADE 700 308 WIN PSS
ACCESSORIES W/STUDS			SCOPE BASE		

FROM:

SHIP TO:

CITY OF BRECKSVILLE
 POLICE DEPARTMENT
 9069 BRECKSVILLE ROAD
 BRECKSVILLE OH 44141

CITY OF BRECKSVILLE
 POLICE DEPARTMENT
 9069 BRECKSVILLE ROAD
 BRECKSVILLE OH 44141

CUST NO: 096728 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER NC

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☒ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
------------------	------	----------	--------	----------	-----	---------

CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3			E1	F2
BARREL ASSY.					E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt rifle in inspection. Trigger would not actuate. Examination revealed that rust was found inside of the trigger housing assembly. The spring in the unit is second place near the trigger. The trigger adjustment screw has been removed. The trigger was found to be damaged by the rust. Rust found on screw.

COMMENTS

Follow cleaning instructions on page 12 of the manual. Attach Manual. Spring connects trigger assembly and. Characteristic is good. Good will. Spring firing will occur. Vague via phone 4/29/94.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD8825 REV. 1/94

BARBER - Kinzer PPS GAL RE0000661

PPS 00656