

FTT - 67 079
449

F.I. YES GUN EXAMINATION REPORT NUMBER: 37 MODEL: 700 BDL L.H.
 GENERAL CONDITION: SLIGHTLY WORN R #: 28088
 OUTSIDE WORK: SCOPE MOUNTED DATE: 11-22-82
 FIRED AMMO TYPE: UNKNOWN FROM: CANTON LAND CO.
908 Tenth & Commercial Ave.
Suite 350
17005 Dallas, TX 75228
 & CONDITION: _____ GUN #: 6859417
 PROOF: R.E.P. 2 INSP.: 123 TEST: 63 CODE: 5-76
 HEADING: O.K. GA./CAL.: .270 WIN.
 BREACH OPENING: O.K. CHECKED BY: SAW
 RECOIL SHOULDERS: O.K. APPROVED: PAH 12/18/82
 CHAMBER: O.K. APPROVED: W 12/18/82
 TEST: _____ APPROVED: PAH 12/23/82
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: RWB 12-23-82

COMPLAINT: "... Rifle Fired When I Was Trying To Unload It..."

INCIDENT: MOVED THE SAFETY TO THE OFF POSITION
TO OPEN THE BOLT.

COMMENTS: Replace fire control as requested by
customer.