

RECEIVING AND ESTIMATING REPORT									
INITIAL		CUSTOMER ORDER NO.		COMMENTS					
B*				WOG 3 OF 3					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER			
02/07/89	02/22/89	KI 5-88	A6302262	700	7MM	ADL/MAG	R	89-06846	
ACCESSORIES		W/STUDS		W/SWIVELS		SCOPE BASE			
FROM:					SHIP TO:				
CLIFF'S RIFLE SHOP 147 SOUTH AIRPORT RD TRAVERSE CITY MI 49684					CLIFF'S RIFLE SHOP 147 SOUTH AIRPORT RD TRAVERSE CITY MI 49684				
ACCOUNT NUMBER		ACCOUNT NUMBER N/C		WRITE <input type="checkbox"/>		PROM. DATE		ESTIMATED	
						3-6-89		UPS	
<p>DEAR CUSTOMER:</p> <p>WE ARE RIGHT IN THE MIDDLE OF OUR MOST BUSY TIME OF THE YEAR IN SERVICING GUN RETURNS FROM ACROSS THE USA AND CANADA. IF OUR REPAIR TURNAROUND TIME IS A BIT LONGER THAN USUAL, IT IS BECAUSE WE WILL NEVER CUT CORNERS JUST TO RUSH THE GUN BACK TO YOU. WE ALWAYS STRIVE TO GIVE YOU A QUALITY REPAIR IN COMBINATION WITH AS TIMELY A GUN RETURN AS POSSIBLE. SO PLEASE BEAR WITH US AND THANK YOU FOR YOUR SUPPORT.</p>									
REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL				
GUN CONDITION: <input type="checkbox"/> NEW <input type="checkbox"/> SLIGHTLY WORN <input type="checkbox"/> VERY WORN <input type="checkbox"/> MISUSED <input type="checkbox"/> MARRED									
CUSTOMER'S REQUEST <i>Fires at random, Repair it</i>									
MAIN FAULT									
PARTS									
<div style="text-align: center;"> <i>Hold for steel</i> </div>									
REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTERN			
GALLERY TESTER		DATE	DATE	DATE	DATE	DATE			

OFFICE COPY

RD4925 REV