

Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
GENERAL CONDITION: NEW R #: 14966
OUTSIDE WORK: No DATE: 7-28-71
FROM: COAST TO COAST ^{STORES}
FIRED AMMO TYPE: - NAMPA, IDAHO
& CONDITION: _____ GUN #: 115149
PROOF: R.E.P. ^{ASSEMBLER V} INSP.: 94 TEST: 55 CODE: PR = 6/68
HEADING: O.K. GA./CAL.: 243 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SAFETY BROKEN. SEAL BROKEN ON ENGAGEMENT
SCREW.

COMPLAINT: "FIRES WITH SAFETY IN ON POSITION"

INCIDENT: FIRES ON SAFE.

COMMENTS: WITH THE CAM BROKEN OFF THE SAFETY COULD
NOT PREVENT FIRING.