

CUSTOMER ORDER NO.		DATE RECEIVED		DATE OPENED		DATE CODE		SERIAL NUMBER		NEW SERIAL NUMBER		MODEL AND GRADE	
		28/93		06/02/93		B1-76		A6252B74				700 22-250 BDL/VAR	
SERIES		W7STBDS		SCOPE		BASE							

Set up file

DALES GUNS
9861 DYER ST 7
EL PASO TX 79924

SHIP TO:

DALES GUNS
9861 DYER ST 7
EL PASO TX 79924

CUST. NO: 029576 C.O.D.L.

JNT NUMBER	ACCOUNT NUMBER NYC	WRITE ☐	PROM. DATE	ESTIMATED	VIA
					UPS

CONDITION	REPAIR CHARGE
NEW	25.00
SLIGHTLY WORN	EXCISE
DIRTY	TAX
DIRTY WORN	INSURANCE
UNREPAIRABLE	UPS
REPAIRED	PARCEL POST
	TOTAL

COMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	rifle discharges when the safety is disengaged.				
GER GROUP		B2			E1	F1
ASSY.		B3			E2	F2
EL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
			C1	D3	E5	F5
			C2			

Upon receipt trigger bar, would not retract. Examination under
my study, gunny, submachine on action, bolt stop, manual, and
the hammer. Trigger adjustment seems again to have been tampered with
and is needed. Trigger pull about minimum spec. Left side 19/46
Trigger pull - low 2 lbs
Trigger pull - .010

COMMENTS

Explain complete trigger assembly
at 1/2 normal replacement cost, as
quality of good unit. Clean action
Go ahead per phone 7/16/93 Mr. Benard

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
63					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV 1/92