

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-01826

INITIAL CUSTOMER ORDER NO.

JJM

ATTN DENNIS SANITA CALL TAG
NO CORR

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/13/94	01/14/94	DY 9-74	6784235		700 25-06 EDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

DOCKERY, BERTEL
RT 3 BOX 746
GROESBECK

TX 76642

DOCKERY, BERTEL
RT 3 BOX 746
GROESBECK

TX
76642

JUST NO: 090636 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

TE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4			E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

IN FAULT

Call mfg 1974. Upon receipt, unable to duplicate customer concern. Examination revealed that the action is slipping with a heavy running resistance. But stop release will not retract. Trigger normally firing.

COMMENTS

Replace complete trigger assembly and clean action at 1/2 normal replacement cost, superior of good work.

Go ahead - per phone 1/15/94 with Mr. [Signature]

REPAIRMAN

PROOF

CLEAN

TEST

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6825 REV. 1/92