

321 RECEIVING and ESTIMATE REPORT

ORDER # **699**

RECEIVED **12-12-78** ESTIMATED **UP** CHARGE **MAI** **1979**

FROM **Ken Dunn**

4001 W. Paradise Ln, Phoenix, Ariz

MODEL and GRADE **700 BDL** **25-06 Rev** SERIAL NO. **A6281747** DATE CODE **CI**

GRADE CODE **4-76**

OR COMPUTER REPAIR ONLY **w/Scope mtr** REPAIR CHG. **80.55**

INS. **PT**

PARCEL POST

MAIN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quote)

CUSTOMER'S COMPLAINT **Repair**

MAIN FAULT **Repair**

GALLERY REPORT

26150 - bigger housing at SW

33391 - stock assembly

4th Test for Malfunction

1-week done

(Check) (Test) (Target)

Repairman **[Signature]** **MAR 15 1979**